



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3249P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	GRIP-FRONT DOOR OUTSIDE R	CUT	234.80	234.80
1	MOULDING ASSY-W/LINE RR D	CUT	166.20	166.20
1	MOULDING ASSY-W/LINE FRT	CUT	110.10	110.10
1	MOULDING ASSY-SIDE SILL R	TO REPAIR SEE LABOUR	290.00	-
	LESS 20% DISCOUNT		-160.22	-102.22
			640.88	408.88
<u>NETT ITEMS</u>				
1	FRT DOOR LOGO CTPL (N)	CUT	75.00	75.00
1	REAR DOOR APPS LOGO (N)	NECESSARY	80.00	80.00
	LESS 10% DISCOUNT		-15.50	-15.50
			139.50	139.50
<u>LABOUR</u>				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF MOULDING ASSY-SIDE SILL R.		700.00	525.00
	SPRAYPAINT CHARGE.		600.00	600.00
			1,300.00	1,125.00
GRAND TOTAL			2,080.38	1,673.38
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,350.00

Report Ref No. NS/INC22001914/Tvcn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.