



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 4333H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRT BUMPER LOWER GRILLE	NOT NECESSARY	438.00	-
1	FRT BUMPER CENTRE GRILLE	CUT	166.90	166.90
1	FRONT BUMPER COVER	TORN	499.90	499.90
10	FRONT BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
2	FRONT BUMPER HOLE COVER	NOT NECESSARY	127.50	-
1	BONNET	BENT	950.50	950.50
1	HEADLAMP LH	NOT NECESSARY	2,735.28	-
1	FRT BUMPER LOGO EMBLEM	NECESSARY	88.00	88.00
	LESS 25% DISCOUNT		-1,257.02	-431.83
			3,771.06	1,295.47
<u>SPECIAL NETT ITEMS</u>				
1	FRONT NUMBER PLATE W/HOLDER (SN)	NOT NECESSARY	55.00	-
			55.00	-
<u>LABOUR</u>				
	PANEL BEATING.		550.00	350.00
	SPRAY PAINTING.		500.00	500.00
	CHECK LIGHTING.	NOT NECESSARY	60.00	-
			1,110.00	850.00
GRAND TOTAL			4,936.06	2,145.47
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,700.00

Report Ref No. NS/INC22001916/Ttcn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.