

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22001917/EVCE2

Date: 18/05/2022

REFERENCE

Insured/Claimant:	CHUA SOCK KOONG	Policy No:	1900012064		
Date of Loss:	25/02/2022	Nature of Claim:	OD	Claim No:	3171031970SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKC900G	Engine No:	CYR070461
Make & Model:	AUDI Q7, 2.0 TFSI QU (A)	Chassis No:	WAUZZZ4M6JD061097
Reg. Date:	08/02/2019 (Man. Year: 2018)	Odometer:	12420 km
Colour:	Grey		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$205,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/55 R19	Rear Tyre Size:	255/55 R19
Front Left Side:	Goodyear 5 mm	Rear Left Side:	Goodyear 5 mm
Front Right Side:	Goodyear 5 mm	Rear Right Side:	Goodyear 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,863.00	13,518.64	12,344.36	47.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,322.00	3,522.00	2,800.00	44.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,185.00	17,040.64	15,144.36	47.05
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	31,685.00	16,540.64	15,144.36	47.80
+ GST 7.00/7.00% (S\$)	2,217.95	1,157.84	1,060.11	47.80
Nett Amount (S\$)	33,902.95	17,698.48	16,204.47	47.80

INSPECTION

Date of Assignment:	01/03/2022		
Date Inspected:	01/03/2022	Inspected At:	24 Benoi Sector Singapore 629857 Premium Automobiles Pte Ltd
Estimated Period of Repair:	4.0 days		

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Crushed	2,896.00 FS	*2,316.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	468.00 FS	*- FS
3	1		*FRONT BUMPER AIR GUIDE - LH / RH	Not Necessary	75.00 FS	*- FS
4	1		*FRONT BUMPER END CAP - LH	Not Necessary	40.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - UPPER CENTER	Not Necessary	309.00 FS	*- FS
6	1		*FRONT BUMPER GRILLE - LOWER CENTER	Not Necessary	230.00 FS	*- FS
7	1		*FRONT BUMPER UNDERRUN BAR	Not Necessary	899.00 FS	*- FS
8	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	Not Necessary	235.00 FS	*- FS
9	1		*FRONT BUMPER SPOILER - LH	Cut	154.00 FS	*123.20 FS
10	1		*FRONT BUMPER SPOILER - LH OUTER	Not Necessary	49.00 FS	*- FS
11	1		*RADIATOR GRILLE	Not Necessary	2,741.00 FS	*- FS
12	1		*RADIATOR GRILLE INNER COVER	Not Necessary	69.00 FS	*- FS
13	1		*RADIATOR GRILLE UPPER COVER	Not Necessary	81.00 FS	*- FS
14	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Missing	332.00 FS	*265.60 FS
15	1		*FRONT BUMPER END CAP - LH	Necessary	38.00 FS	*29.84 FS
16	4		*SPRING CLIP - LH	Necessary	4.00 FS	*2.88 FS
17	1		*RADIATOR SPOILER - INNER LH	Not Necessary	64.00 FS	*- FS
18	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	192.00 FS	*- FS
19	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	1,025.00 FS	*- FS
20	2		*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	81.00 FS	*- FS
21	1		*FRONT BUMPER GUIDE SECTION UPPER - LH	Broken	50.00 FS	*39.52 FS
22	1		*FRONT BUMPER TOP COVER	Not Necessary	146.00 FS	*- FS
23	1		*CAUTION STICKER	Not Necessary	16.00 FS	*- FS
24	1		*AIR COND STICKER	Not Necessary	9.00 FS	*- FS
25	1		*HORN BRACKET - LH	Not Necessary	240.00 FS	*- FS
26	2		*FRONT PARKING AID SENSOR - INNER / OUTER	Not Necessary	488.00 FS	*- FS
27	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	10.00 FS	*- FS
28	1		*FRONT FENDER - LH	Dented	1,819.00 FS	*1,455.20 FS
29	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	79.00 FS	*- FS
30	1		*FRONT FENDER BRACE - LH	Bent	120.00 FS	*95.60 FS
31	1		*FRONT FENDER BRACKET - LH	Not Necessary	72.00 FS	*- FS
32	1		*FRONT WHEEL HOUSING LINER - LH	Not Necessary	260.00 FS	*- FS
33	1		*REAR WHEEL HOUSING LINER - LH	Not Necessary	260.00 FS	*- FS
34	1		*HEADLIGHT MOUNTING - LH	Broken	132.00 FS	*105.20 FS
35	1		*HEADLIGHT - LH	Broken	10,660.00 FS	*8,528.00 FS
36	1		*LIFT CYLINDER - LH	Not Necessary	217.00 FS	*- FS
37	1		*LIFT CYLINDER HOSE - LH	Not Necessary	113.00 FS	*- FS
38	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	5.00 FS	*- FS
39	1		*RADIATOR AIR GUIDE - LH	Not Necessary	33.00 FS	*- FS
40	1		*RADIATOR AIR GUIDE - UPPER	Not Necessary	48.00 FS	*- FS
41	1		*RADIATOR AIR GUIDE - LOWER	Not Necessary	48.00 FS	*- FS
42	2		*FRONT WHEEL ARCH COVER - LH / RH	Necessary	696.00 FS	*556.80 FS
43	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
44	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **25,863.00** **13,518.64**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	450.00	450.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,700.00	1,200.00
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	2,500.00	1,200.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			6,322.00	3,522.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >