

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22001922/APA3Q2**Date:** 02/12/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210054623
<b>Claimant Vehicle No :</b>	YP9221P	<b>Insured Vehicle No :</b>	GBD1560Z
Date of Loss:	01/03/2022	Nature of Claim:	TP
		Claim No:	9088406798SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>YP9221P</b>		
Make & Model:	MITSUBISHI CANTER, 3.0 D FEB21ER4SDEN (M)	Engine No:	4P10D25415
Reg. Date:	24/07/2018 (Man. Year: 2018)	Chassis No:	FEB21EA25265
Colour:	White	Odometer:	80103 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/85 R15	Rear Tyre Size:	195/85 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	20,287.80	7,006.40	13,281.40	65.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,640.00	2,380.00	1,260.00	34.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>23,927.80</b>	<b>9,386.40</b>	<b>14,541.40</b>	<b>60.77</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,500.00</b>		
<b>(S\$)</b>	23,927.80	6,500.00	17,427.80	72.83
<b>+ GST 7.00/7.00% (S\$)</b>	1,674.95	455.00	1,219.95	72.84
<b>Nett Amount (S\$)</b>	<b>25,602.75</b>	<b>6,955.00</b>	<b>18,647.75</b>	<b>72.83</b>
<b>+ Loss of Use (9.0 x S\$100.00/day) (S\$)</b>		900.00		
<b>+ Doc/Search Fee (S\$)</b>		36.45		
<b>Nett Liability (S\$)</b>		<b>7,891.45</b>		

INSPECTION

Date of Assignment:	02/03/2022	
Date Inspected:	02/03/2022 Inspected At:	Ryder Auto Pte Ltd (HQ) 2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit Singapore 417921
Estimated Period of Repair:	7.0 days	

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

*ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR O/S PILLAR	Repair	800.00 FS	*- FS
2	1		*O/S BOX REAR DOOR PANEL	Dented	1,500.00 FS	*1,400.00 FS
3	3		*O/S BOX REAR DOOR PANEL HINGES	Not Necessary	300.00 FS	*- FS
4	1		*O/S BOX REAR DOOR PANEL LOCK MIDDLE	Bent	250.00 FS	*250.00 FS
5	1		*O/S BOX REAR DOOR PANEL STICKER	Necessary	150.00 FS	*150.00 FS
6	1		*N/S BOX REAR DOOR PANEL	Not Necessary	1,500.00 FS	*- FS
7	3		*N/S BOX REAR DOOR PANEL HINGES	Not Necessary	300.00 FS	*- FS
8	1		*N/S BOX REAR DOOR PANEL LOCK MIDDLE	Not Necessary	250.00 FS	*- FS
9	1		*N/S BOX REAR DOOR PANEL STICKER	Not Necessary	150.00 FS	*- FS
10	1		*REAR TAIL-GATE LOWER WOODEN CROSS MEMBER	Cracked	500.00 FS	*450.00 FS
11	1		*REAR O/S & N/S STOPPER	O/S Cut	180.00 FS	*90.00 FS
12	1		*REAR STEP	Cracked	150.00 FS	*150.00 FS
13	2		*REAR STEP BOLT	Bent	100.00 FS	*50.00 FS
14	1		*REAR O/S & N/S LONG WOODEN MEMBER	O/S Cracked	1,400.00 FS	*600.00 FS
15	1		*REAR O/S & N/S WOODEN MEMBER U-BOLT (8PCS)	Bent (3Pcs Only)	800.00 FS	*300.00 FS
16	1		*REAR O/S & N/S TAIL-LAMP BRACKET	O/S Bent	260.40 FL	*130.20 FL
17	1		*REAR O/S & N/S TAIL-LAMP	O/S Cracked	610.00 FL	*305.00 FL
18	1		*RIVETS (60PCS)	Necessary	60.00 FS	*40.00 FS
19	1		*REAR REG. NO. PLATE	Not Necessary	45.00 FS	*- FS
20	1		*REAR LTA REAR GUARD	Bent	1,800.00 FS	*800.00 FS
21	1		*REAR LTA REAR GUARD STEP	Bent	500.00 FS	*350.00 FS
22	1		*O/S PANEL	Repair	3,400.00 FS	*- FS
23	1		*O/S PANEL STICKER	Necessary	800.00 FS	*550.00 FS
24	1		*REAR CARRIDGE FLOOR PLANKS (14FT CHENGAL) (8PCS)	Cracked (3Pcs Only)	3,200.00 FS	*900.00 FS
25	1		*REAR HORIZONTAL CROSS MEMBER (SHORT) (6PCS)	Cracked (3Pcs Only)	1,500.00 FS	*600.00 FS
26	1		*REAR N/S LONG WOODEN MEMBER (NPA)	Repeated	0.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>20,505.40</b>	<b>7,115.20</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	217.60	108.80
<b>Total Parts (\$)</b>	<b>20,287.80</b>	<b>7,006.40</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPAIR FRONT CABIN PANEL DISMANTLE, STRAIGHTEN AND WELDING DAMAGE PARTS	New	1,800.00	1,400.00
2	TO SPRAY PAINTING	New	500.00	400.00
3	TO REMOVE AND REFIT REAR CARRIAGE TO FACILITATE CHANGING WOODEN CROSS MEMBER	New	300.00	0.00
4	PROVIDE LIFTING EQUIPMENT TO REMOVE REAR CARRIAGE	New	800.00	500.00
5	TO CHECK WIRING	New	120.00	30.00
6	TO RE-SEAL ANTI-RUST	New	120.00	50.00
<b>Gross Labour Cost (S\$)</b>			<b>3,640.00</b>	<b>2,380.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >