

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS22001923/UTY3N2**Date:** 16/03/2022REFERENCE

Handling Insurer: ECICS Limited Policy No: MPC21P00142700
Claimant Vehicle No : SMW1221Y **Insured Vehicle No :** SGK5376S
 Date of Loss: 28/02/2022 Nature of Claim: TP Claim No: DMPC2200087H/02/JT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMW1221Y**
 Make & Model: HONDA SHUTTLE, 1.5 G CVT (A) Engine No: L15B6023189
 Reg. Date: 12/08/2020 (Man. Year: 2019) Chassis No: GK82102710
 Colour: White Odometer: 67580 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60R15 Rear Tyre Size: 185/60R15
 Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
 Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,212.10	8,486.40	12,725.70	59.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,810.00	2,520.00	2,290.00	47.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,022.10	11,006.40	15,015.70	57.70
Approved Total (Overridden) (S\$)		8,800.00		
(S\$)	26,022.10	8,800.00	17,222.10	66.18
+ GST 7.00/7.00% (S\$)	1,821.55	616.00	1,205.55	66.18
Nett Amount (S\$)	27,843.65	9,416.00	18,427.65	66.18

INSPECTION

Date of Assignment: 01/03/2022
 Date Inspected: 01/03/2022 Inspected At: Fastech Auto Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
 Singapore 417883
 Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 16 Mar 2022)	
Parts:	N/A	HONDA SHUTTLE 1.5 G CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMW1221Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed/Torn	1,193.00 F	*923.90 FL
2	1		*FRONT BUMPER SIDE RETAINER N/S	Necessary	66.50 F	*55.20 FL
3	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*45.00 FL
4	1		*FRONT BUMPER BEAM	Not Necessary	341.00 F	*- FL
5	1		*HEADLAMP N/S	Holder Cracked	2,650.00 F	*2,315.60 FL
6	1		*HEADLAMP LOWER BRACKET N/S	No such part	85.50 F	*- FL
7	1		*FRONT FENDER N/S	Badly Dented	685.20 F	*455.50 FL
8	1		*FRONT FENDER INNER SHIELD N/S	Torn	245.20 F	*188.50 FL
9	1		*SET FRONT FENDER INNER SHIELD CLIPS N/S	Necessary	50.00 F	*45.00 FL
10	1		*FRONT FENDER INNER GARNISH N/S	Deformed	121.30 F	*105.30 FL
11	1		*FRONT FENDER INNER PANEL N/S	Repair	485.20 F	*- FL
12	1		*FRONT SHOCK ABSORBER N/S	Bent	665.20 F	*380.50 FL
13	1		*FRONT LOWER ARM N/S	Bent	685.40 F	*422.30 FL
14	1		*FRONT KNUCKLE ARM N/S	Warped	605.20 F	*345.50 FL
15	1		*FRONT KNUCKLE ARM BEARING N/S	Damaged	350.00 F	*182.00 FL
16	1		*FRONT DRIVE SHAFT N/S	Not Necessary	1,128.30 F	*- FL
17	1		*FRONT DOOR N/S	Distorted	1,485.20 F	*899.50 FL
18	2		*FRONT DOOR HINGES	Bent/Twisted	210.00 F	*196.00 FL
19	1		*FRONT DOOR CHECKER N/S	Twisted	145.00 F	*121.00 FL
20	1		*FRONT DOOR INNER LOCK N/S	Shorted/Damaged	395.00 F	*295.00 FL
21	1		*FRONT DOOR OUTER HANDLE N/S	Not Necessary	288.30 F	*- FL
22	1		*FRONT DOOR INNER TRIM BOARD N/S	Deformed/Torn	681.20 F	*588.20 FL
23	1		*SET FRONT DOOR INNER TRIM BOARD CLIPS N/S	Necessary	50.00 F	*50.00 FL
24	1		*FRONT DOOR GLASS OUTER MOULDING N/S	Serviceable	108.30 F	*- FL
25	1		*FRONT DOOR GLASS REGULATOR N/S	Bent	323.20 F	*245.50 FL
26	1		*FRONT DOOR GLASS REGULATOR MOTOR N/S	Jammed	650.00 F	*480.00 FL
27	1		*FRONT DOOR MIRROR ASSY N/S	Repair	845.20 F	*- FL
28	1		*FRONT DOOR INNER RUBBER N/S	Necessary	242.30 F	*168.30 FL
29	1		*FRONT DOOR OUTER PILLAR N/S	Badly Dented	899.30 F	*715.20 FL
30	1		*SET FRONT DOOR FRAME BLACK STICKER N/S	Necessary	60.00 F	*60.00 FL
31	1		*REAR DOOR N/S	Repair	1,322.30 F	*- FL
32	1		*REAR DOOR GLASS OUTER MOULDING N/S	Serviceable	108.80 F	*- FL
33	1		*ROCKER PANEL GARNISH N/S	Torn	850.00 F	*650.00 FL
34	1		*SET ROCKER PANEL GARNISH CLIPS N/S	Necessary	50.00 F	*50.00 FL
35	1		*ROCKER PANEL N/S	Repair	685.20 F	*- FL
36	1		*CENTRE PILLAR N/S	Repair	655.80 F	*- FL
37	1		*SET FRONT SPORT RIM	N/s Cut/Bent	1,500.00 FS	*500.00 FS
38	1		*FRONT TYRE	Serviceable	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	21,212.10	10,483.00
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	1,996.60
Total Parts (\$)	21,212.10	8,486.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE	New	180.00	120.00
3	TO DISMANTLE & REFIX DOOR MECHANISM	New	180.00	60.00
4	TO CONDUCT WHEEL ALIGNMENT	New	150.00	80.00
5	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	100.00
6	TO SPRAY RUST PROOFING	New	150.00	90.00
7	TO RESET & REPROGRAMME SYSTEM	New	180.00	50.00
8	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,800.00	800.00
9	TO PUTTY & SPRAY PAINTING	New	2,000.00	1,200.00
Gross Labour Cost (S\$)			4,810.00	2,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >