

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	ALLIANZ INSURAN	ICE SINGAPORE PTE LTD	Ref:	CS3/AIS22001926/Vvy3e2	
	79 ROBINSON ROAD #09-01 SINGAPORE 068897		Date:	16/03/2022	
			Code	AIS	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SMC 7360U	Veh. Inspected	SLE 6781X	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	BISAISCL2022-00434SL	Excess (\$)	0.00	
	Assign From	SHANTI	Assign Date	01/03/2022	
2.	Vehicle Particulars & Condition				
	Make & Model	MAZDA 5	c.c	1998	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	JM6CW1071G0124090	Colour	BLUE	
	Odometer	97779 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	205/55 R16	WEST LAKE	5 mm	
	L/H Front Tyre	205/55 R16	WEST LAKE	5 mm	
	R/H Rear Tyre	205/55 R16	WEST LAKE	5 mm	
	L/H Rear Tyre	205/55 R16	WEST LAKE	5 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRO		ONT PORTION.		
5.	General Information				
	Accident Date	21/02/2022	Inspect Date / Time	01/03/2022 (05:00 PM)	
	Survey held at	GARAGE 13 PTE LTD			
		8 KAKI BUKIT AVE 4 #03-46 PREMIER SINGAPORE 415875			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000				
5b.	Estimate Days of Repair				
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days			

Report Ref No. CS3/AIS22001926/Vvy3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

L

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser