

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI22001928/UNY3E2

**Date:** 10/08/2022

### REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00077462100

**Claimant Vehicle  
No :** SMJ6782E

**Insured Vehicle  
No :** SGT9156L

Date of Loss: 27/01/2022

Nature of Claim: TP

Claim  
No: SNM22D200719/C02/CSC

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMJ6782E**

Make & Model: MAZDA 6, 2.0 (A)

Reg. Date: 15/03/2019 (Man. Year: 2018)

Colour: Red

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: PE21257482

Chassis No: JM6GL1072K0312110

Odometer: 11404 km

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/55 R17

Front Left Side: Bridgestone 8 mm

Front Right Side: Bridgestone 8 mm

*The above values represent the remaining tyre treads depth*

Rear Tyre Size: 225/55 R17

Rear Left Side: Bridgestone 8 mm

Rear Right Side: Bridgestone 8 mm

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,181.70	565.40	6,616.30	92.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,290.00	4,735.00	5,555.00	53.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>17,471.70</b>	<b>5,300.40</b>	<b>12,171.30</b>	<b>69.66</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,223.02</b>	<b>371.03</b>	<b>851.99</b>	<b>69.66</b>
<b>Nett Amount (S\$)</b>	<b>18,694.72</b>	<b>5,671.43</b>	<b>13,023.29</b>	<b>69.66</b>

### INSPECTION

Date of Assignment: 29/03/2022

Date Inspected: 03/03/2022

Estimated Period of Repair: 5.0 days

Inspected At:

Trans Eurokars Pte Ltd (Ubi)  
5 Ubi Close  
Singapore 408605

**Adjuster:** MARCUS CHUA

**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 10 Aug 2022)
<b>Parts:</b>	143	MAZDA 6 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMJ6782E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH	Dented	383.70 F	*383.70 F
2	1		*GUARD LHF MUD GL3	Distorted	114.30 F	*114.30 F
3	10		*MUD GUARD LH FRT CLIPS	Necessary	30.00 F	*30.00 F
4	1		*FRONT DOOR LH	Repair	975.20 F	*- F
5	1		*STRIPE NO.1(L), BODY SIDE GL	Not Necessary	11.00 F	*- F
6	1		*STRIPE NO.3(L), BODY SIDE GL	Not Necessary	12.90 F	*- F
7	12		*GROMMET, SCREW	Not Necessary	36.00 F	*- F
8	1		*GROMMET, SCREW	Not Necessary	3.80 F	*- F
9	5		*FASTENER	Not Necessary	36.00 F	*- F
10	1		*REAR DOOR LH	Repair	1,312.10 F	*- F
11	1		*STRIPE NO.4(L), BODY SIDE GL	Not Necessary	15.50 F	*- F
12	1		*STRIPE NO.2(L), BODY SIDE GL	Not Necessary	11.90 F	*- F
13	10		*GROMMET, SCREW	Not Necessary	30.00 F	*- F
14	1		*GROMMET, SCREW	Not Necessary	3.80 F	*- F
15	5		*FASTENER	Not Necessary	36.00 F	*- F
16	1		*STONE GUARD LH	Scratched	17.40 F	*17.40 F
17	1		*GARNISH LH FRONT DOOR	Not Necessary	99.10 F	*- F
18	1		*GARNISH LH REAR DOOR	Not Necessary	110.20 F	*- F
19	1		*GARNISH LH RR DOOR	Not Necessary	54.60 F	*- F
20	8		*CLIP, GARNISH	Not Necessary	98.40 F	*- F
21	1		*COVER ROCKER PANEL LH	Repair	198.00 F	*- F
22	1		*WHEEL, DISC 17X7	Repair	1,196.80 F	*- F
23	1		*REAR ABSORBER LH	Not Necessary	322.20 F	*- F
24	1		*LOWER ARM LH REAR	Not Necessary	273.30 F	*- F
25	1		*UPPER ARM LH REAR (NPA)	Not Necessary	0.00 F	*- F
26	1		*LATERAL LINK LH REAR	Not Necessary	116.30 F	*- F
27	1		*TRAILING LINK LH REAR	Not Necessary	353.50 F	*- F
28	1		*KNUCKLE LH REAR	Not Necessary	799.30 F	*- F
29	1		*HUB WHEEL BEARING LH REAR	Not Necessary	480.40 F	*- F
30	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett.

<b>Total Parts (S\$)</b>	<b>7,181.70</b>	<b>565.40</b>
--------------------------	-----------------	---------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO RESPRAY FRONT FENDER LH, FRONT & REAR DOOR LH, REAR FENDER LH, ROCKER PANEL LH AND ALL AREAS AFFECTED BY THE ACCIDENTS	New	3,780.00	2,835.00
2	TO TRANSFER THE DOOR MECHANISM	New	660.00	0.00
3	TO REPLACE AXLE AND SUSPENSION MECHANISM	New	660.00	0.00
4	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT	New	560.00	280.00
5	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING	New	120.00	0.00
6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	120.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	300.00	180.00
8	TO REPLAC FRONT FENDER LH, FRONT & REAR DOOR LH. TO REPAIR REAR FENDER LH, ROCKER PANEL LH AND ALL AREAS AFFECTED BY THE ACCIDENTS	New	3,960.00	1,320.00
<b>Gross Labour Cost (\$\$)</b>			<b>10,290.00</b>	<b>4,735.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >