

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/190R GS1 Reg. No. 19-900/190-R				
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref	f: CS/AGI22001934/Dny3m4	
	(BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Daf	te: 04/08/2022	
			Cod	de: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMQ 5041E	Veh. Inspected	SHC 8764R	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10014058/JM	Excess (\$)	0.00	
	Assign From	FRAULEINE KHOO	Assign Date	01/03/2022	
2. Vehicle Particulars & Condition					
	Make & Model	HYUNDAI I40	c.c	1685	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	KMHLB41UMGU083374	Colour	BLUE	
	Odometer	838460 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	205/60 R16	WEST LAKE	5 mm	
	L/H Front Tyre	205/60 R16	WEST LAKE	5 mm	
	R/H Rear Tyre	205/60 R16	WEST LAKE	5 mm	
	L/H Rear Tyre	205/60 R16	WEST LAKE	5 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5.	5. General Information				
	Accident Date	26/02/2022	Inspection Date	02/03/2022	
	Survey held at BLK 9 SECTOR C #01-42, SIN MING INDUSTRIAL ESTATE				
	Repairer	Repairer BIFROST AUTO PTE LTD			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

7 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: