

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 4902P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BONNET (WCP)	BENT	280.00	280.00
2	BONNET HINGE LH / RH @\$40.00 (WCP)	TO REPAIR SEE LABOUR	80.00	-
1	BONNET LOCK (WCP)	SERVICEABLE	60.00	-
1	BONNET LOGO BADGE (WCP)	NECESSARY	35.00	35.00
1	CENTER GRILLE (WCP)	SERVICEABLE	130.00	-
1	FRONT BUMPER (WCP)	TO REPAIR SEE LABOUR	180.00	-
2	FRONT SIDE RETAINER LH / RH @\$45.00 (WCP)	NECESSARY	90.00	90.00
1	HEADLAMP LH (WCP)	CRACKED	400.00	400.00
1	RADIATOR TOP GARNISH (WCP)	SERVICEABLE	70.00	-
1	SUPPORT PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT BUMPER SPONGE (ADDITIONAL) (WCP)	CUT	50.00	50.00
	COST PLUS 10%		137.50	85.50
			1,512.50	940.50
	SPECIAL NETT ITEMS			
1	FRONT BUMPER CLIPS (SN)	NECESSARY	35.00	20.00
1	FRONT CARPLATE WITH HOLDER (SN)	NECESSARY	35.00	35.00
1	CENTER GRILLE CLIPS (SN)	NECESSARY	25.00	15.00
			95.00	70.00
	<u>LABOUR</u>			
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS. INCLUSIVE OF THE REPAIR OF BONNET HINGE LH / RH, FRONT BUMPER AND SUPPORT PANEL.		800.00	400.00
	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED & REPAIRED.		600.00	300.00

Report Ref No. CS6/AIS22001939/Vty3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO REMOVE / REFIX / REPLACE WIRING SYSTEM AT ACCIDENT DAMAGED AREA AND CHECK FOR ALL ELECTRICAL PROPER FUNCTION.		30.00	20.00
			1,430.00	720.00
	GRAND TOTAL		3,037.50	1,730.50

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		1,400.00
LESS EXCESS		-600.00
NETT LIABILITY		800.00

Report Ref No. CS6/AIS22001939/Vty3e2



THEVAN THOMAS KARTHIKESAVAN

X:2.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser