### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

Our File No: CC3/AIG22001941/TVCE2

AIG Building, 78 Shenton Way, #09-16

Singapore 079120 Date: 30/05/2022

**REFERENCE** 

Insured/Claimant: LIM CHEE SIONG Policy No: 1700093804

Date of Loss: 25/02/2022 Nature of Claim: OD Claim No: 0716389343SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SKU881H

Make & Model: AUDI A3, 999cc TFSI S TRONIC (LED) (A) Engine No: CHZ600608

Reg. Date: 27/12/2017 (Man. Year: 2017) Chassis No: WAUZZZ8V5J1030864

Colour: White Odometer: 47066 km

Engine Capacity: 999 cc
Market Value/New Car Price: \$\$84,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 235/35 R19 Rear Tyre Size: 235/35 R19
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		24,987.00	3,126.80	21,860.20	87.49
Miscellaneous Items		0.00	0.00	0.00	
Labour		8,852.00	2,652.00	6,200.00	70.04
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	33,839.00	5,778.80	28,060.20	82.92
	- Excess (S\$)	300.00	300.00	0.00	0.00
	(S\$)	33,539.00	5,478.80	28,060.20	83.66
	+ GST 7.00/7.00% (S\$)	2,347.73	383.52	1,964.21	83.66
	Nett Amount (S\$)	35,886.73	5,862.32	30,024.41	83.66

**INSPECTION** 

Date of Assignment: 01/03/2022

Date Inspected: Premium Automobiles Pte Ltd (UBI)

Date Inspected: 01/03/2022 Inspected At: 55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### **REPAIR DETAILS**

# **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	1,987.00 FS	*1,589.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	195.00 FS	*-FS
3	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Not Necessary	86.00 FS	*-FS
4	1		*FRONT BUMPER LOWER GRILLE - CENTER	Deformed	179.00 FS	*143.20 FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	571.00 FS	*-FS
6	2		*FRONT BUMPER CLOSING ELEMENT - LH / RH	Not Necessary	636.00 FS	*- FS
7	2		*FRONT BUMPER COVER TRIM - LH / RH	Not Necessary	364.00 FS	*- FS
8	2		*FRONT BUMPER ADAPTER - LH / RH	Not Necessary	84.00 FS	*- FS
9	1		*RADIATOR GRILLE	Cracked	1,406.00 FS	*1,124.80 FS
10	1		*RADIATOR GRILLE CLOSING ELEMENT	Deformed	210.00 FS	*168.00 FS
11	1		*CAUTION STICKER	Necessary	16.00 FS	*12.40 FS
12	1		*A/C STICKER	Necessary	9.00 FS	*6.64 FS
13	1		*FRONT BUMPER AIR GRILLE - RH	Not Necessary	210.00 FS	*- FS
14	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	847.00 FS	*- FS
15	1		*FRONT BUMPER REINFORCEMENT FOAM	Not Necessary	211.00 FS	*- FS
16	1		*FRONT BUMPER REINFORCEMENT COVER	Not Necessary	136.00 FS	*- FS
17	1		*HORN - LOW TONE	Not Necessary	213.00 FS	*- FS
18	1		*BONNET	Repair	3,134.00 FS	*- FS
19	1		*BONNET ATTACHMENT PARTS	Not Necessary	172.00 FS	*- FS
20	1		*BONNET EDGE PROTECTION	Not Necessary	31.00 FS	*- FS
21	1		*BONNET CATCH HOOK - UPPER	Not Necessary	100.00 FS	*- FS
22	1		*BONNET STRIKER - RH	Not Necessary	123.00 FS	*- FS
23	1		*BONNET CATCH HOOK - LOWER	Not Necessary	71.00 FS	*- FS
24	1		*BONNET LOCK	Not Necessary	228.00 FS	*- FS
25	1		*BONNET BOWDEN CABLE	Not Necessary	64.00 FS	*- FS
26	1		*BONNET BOWDEN CABLE COVER	Not Necessary	11.00 FS	*- FS
27	1		*FRONT WHEEL HOUSING LINER - RH	Not Necessary	183.00 FS	*-FS
28	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	93.00 FS	*-FS
29	2		*HEADLIGHT - LH / RH	Not Necessary	10,910.00 FS	*- FS
30	2		*HEADLIGHT LIFT CYLINDER - LH / RH	Not Necessary	312.00 FS	*- FS
31	1		*HEADLIGHT LIFT CYLINDER HOSE	Not Necessary	78.00 FS	*- FS
32	1		*LOCK CARRIER	Not Necessary	806.00 FS	*-FS
33	6		*COOLANT	Not Necessary	282.00 FS	*- FS
34	1		*RADIATOR AIR GUIDE - LH / RH	O/S Deformed /N/S NotNecessary	56.00 FS	*22.16 FS
35	1		*RADIATOR AIR GUIDE SEAL	Not Necessary	9.00 FS	*-FS
36	1		*RADIATOR AIR GUIDE - UPPER CENTRE	Not Necessary	14.00 FS	*-FS
37	1		*A/C CONDENSER	Not Necessary	569.00 FS	*-FS
38	1		*TEMPERATURE BRACKET	Not Necessary	21.00 FS	*-FS
39	1		*FRONT NO. PLATE	Dented	60.00 FS	*60.00 FS
40	1		*SUNDRIES	Not Necessary	300.00 FS	*-FS
	anchise	nart S=	SpcNett.		200.0010	

Total Parts (S\$) 24,987.00 3,126.80

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# **Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	700.00	0.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE. VACUUM AND REGAS	New	1,400.00	0.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,200.00	1,000.00
5	TO RESPRAY FRONT BUMPER AND BONNET	New	2,000.00	1,100.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
	Gross Labou	8,852.00	2,652.00	
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >