

ASS. REC. BY:

REF:

AIG / 22001949 / Kc

C

Kenneeth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMP 2232X Yr Regn: 09, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Noah c.c. 1797Colour M.P. White A/C: Insured / Std / NI / NASp. Reading 187332 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 3WR80 0396700Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / 8/Rim / STD A/Rim or

Tyre Size: F: _____

R: 225/45BR17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front _____ Rear _____

R/Bal. 8 mm R/Bal. 8 mmL/Bal. 8 mm L/Bal. 8 mmD.O.A. 28/2/22 D.O.I. 1/3/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

/ GIA not ready18/3 11Pm @ 4850/- Carhu

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

AIG.

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-09 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST & Reg No. 201629438M

28/02/2022

Owner: HYMS CAR LEASING PTE LTD

ESTIMATE TO REPAIR TOYOTA NOAH 1.8X - SMP2232X

Not Notified
11 hrs @ 485dp
Running After Pain
5 days

1pc	rear tailgate	1643	Bt	\$	1,712.85	✓
1pc	rear tailgate "HYBRID" emblem		Mr	\$	132.25	✓
1pc	rear tailgate windscreen moulding		Mr	\$	172.80	✓
1pc	rear tailgate outer chrome		mycm	\$	581.90	✓
1pc	rear tailgate "TOYOTA" logo		Mr	\$	121.10	✓
1pc	rear tailgate inner lock		Mr	\$	581.90	X
1pc	rear tailgate inner rubber		Mr	\$	371.85	X
1pc	rear tailgate inner garnish		mycm	\$	371.75	✓
1pc	rear LH taillamp		CM	\$	781.55	✓
1pc	rear LH taillamp lower garnish		Mr	\$	371.85	✓
1pc	rear LH taillamp lower garnish side retainer		Mr	\$	172.25	✓
1pc	rear LH taillamp inner panel		Mr	\$	381.50	X
1pc	rear bumper	1021.00	Mr	\$	1,217.45	✓
1pc	rear bumper LH side retainer		Mr	\$	172.10	✓
1pc	rear bumper LH side reflector		Mr	\$	181.90	X
10pcs	rear bumper clip @\$5.00		Mr	\$	50.00	✓
1pc	rear end panel LH corner panel		Mr	\$	481.50	X
1pc	rear end panel inner garnish		Mr	\$	378.85	X
1pc	rear fender LH inner garnish		Mr	\$	731.35	X
1pc	rear fender LH top garnish		mycm	\$	481.50	✓

less 25%

1set rear parking sensor
sealant

remove & refit rear windscreen glass

wiring

tuffkote

spray painting

labour charges

Total

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date:

\$ 9,448.20

\$ 2,362.05

\$ 7,086.15

Mr 280.00 X

Mr 80.00 4050

\$ 120.00 ✓

\$ 100.00 201

\$ 100.00 301

\$ 1,200.00 800

\$ 1,200.00 500

\$ 10,166.15

