3/22/22, 11:30 AM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22001959/UTY3N2

**Date:** 22/03/2022

**REFERENCE** 

Handling Insurer: China Taiping Insurance

(Singapore) Pte. Ltd.

Policy No:

DMPCSNW00255572100

**Claimant Vehicle** 

SGL31P

Insured Vehicle No :

EH1038J

Date of Loss:

No:

28/02/2022

Nature of Claim: TP

Claim

Odometer:

SNM22D201464/C02/LEWLC

Yes

75169 km

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SGL31P

 Make & Model:
 MERCEDES-BENZ GLA180, 1.6 (A)
 Engine No:
 27091030912385

 Reg. Date:
 21/06/2016 (Man. Year: 2016)
 Chassis No:
 WDC1569422J235792

Colour: Black

Engine Capacity: 1595 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable):

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 235/50R18 Rear Tyre Size: 235/50R18
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm
Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,051.90	913.50	2,138.40	70.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	830.00	460.00	370.00	44.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$	3,881.90	1,373.50	2,508.40	64.62
Approved Total (Overridden) (S\$	5)	1,100.00		
(5\$	3,881.90	1,100.00	2,781.90	71.66
+ GST 7.00/7.00% (S\$	271.73	77.00	194.73	71.66
Nett Amount (S\$	4,153.63	1,177.00	2,976.63	71.66

<u>INSPECTION</u>

Date of Assignment: 01/03/2022

Date Inspected: 09/03/2022 Inspected At: B

Progressive Car Care Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46

Singapore 408716

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### **REPAIR DETAILS**

#### Reference

3/22/22, 11:30 AM

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Mar 2022)

Parts: M1-SUV MERCEDES-BENZ GLA180 1.6 (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGL31P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,266.00 FL	*- FL
2	1		*REAR BUMPER LOWER BLACK	Serviceable	495.00 FL	*-FL
3	1		*REAR BUMPER LOWER CHROME	Cracked	1,015.00 FL	*1,015.00 FL
4	1		*REAR BUMPER TOP PLATE	Serviceable	235.00 FL	*-FL
5	2		*REAR BUMPER SENSOR-CENTRE	Serviceable	380.00 FL	*- FL
F=Fra	ınchise	part. L=ListIten	nDisc.			
				Sub Total (S\$)	3,391.00	1,015.00
			- List Item Discount on L Ite	ms 10.00/10.00% (S\$)	339.10	101.50
				Total Parts (S\$)	3,051.90	913.50
			Report was unsubmitted duri	ng this print-out.		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO KNOCK OUT DENTS, REMOVE, REPLACE ACCIDENT PARTS	S New	350.00	200.00
2	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	300.00	200.00
3	TO CHECK WIRING	New	50.00	20.00
4	TO TRANSFER REAR BUMPER SENSOR	New	100.00	40.00
5	TO TUFF-KOTE	New	30.00	0.00
	Gross	Labour Cost (S\$)	830.00	460.00
	Report was unsubmitted duri	ng this print-out.		

< END OF ESTIMATES >