4/5/22, 9:48 AM Adjuster Report

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI22001962/KQY3N2

05/04/2022 Date:

**REFERENCE** 

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMHCSNW00014602100

**Claimant Vehicle** No:

SML655T

No:

Insured Vehicle SND1003Z

Date of Loss:

27/02/2022

Nature of Claim: TP

Claim

SNM22D201421/C02/CSC No:

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

SML655T Reg No:

Make & Model: TOYOTA COROLLA ALTIS, 1.6 Elegance 2WD (A)

Engine No: 1ZR0D47063

Odometer:

Reg. Date: 03/05/2019 (Man. Year: 2019) Chassis No: MR053REH604596601

25231 km

Colour: Metallic Red

**Engine Capacity:** 

Sum Insured (S\$):

1598 cc

Market Value/New Car Price: N/A

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes Nο

**CONDITION OF TYRES** 

Front Tyre Size: 215/45R17 Rear Tyre Size: 215/45R17 Front Left Side: Rear Left Side: Michelin 7 mm Michelin 7 mm Front Right Side: Rear Right Side: Michelin 7 mm Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		8,791.95	7,348.50	1,443.45	16.42
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,910.00	2,410.00	500.00	17.18
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	11,701.95	9,758.50	1,943.45	16.61
	Approved Total (Overridden) (S\$)		7,800.00		
	Nett Amount (S\$)	11,701.95	7,800.00	3,901.95	33.34

**INSPECTION** 

Date of Assignment: 29/03/2022

Kay Motor (HQ)

Date Inspected: 02/03/2022 Inspected At: BLK 9 SIN MING INDUSTRIAL ESTATE #01-46

Singapore 565744

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

4/5/22, 9:48 AM Adjuster Report

### **REPAIR DETAILS**

### Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Apr 2022)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 Elegance 2WD (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SML655T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars C	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	531.60 FL	*531.60 FL
2	1		*FRONT BUMPER O/S GARNISH	Cracked	229.40 FL	*229.40 FL
3	1		*FRONT BUMPER FOG LAMP	Serviceable	310.40 FL	*-FL
4	1		*FRONT BUMPER O/S SIDE RETAINER	Distorted	68.20 FL	*68.20 FL
5	1		*O/S HEAD LAMP	Cut	3,970.80 FL	*2,999.80 FL
6	1		*O/S FRONT FENDER	Bent	908.90 FL	*908.90 FL
7	1		*O/S FRONT FENDER INNER SHIELD	Distorted	227.80 FL	*227.80 FL
8	1		*O/S FRONT FENDER VVTI EMBLEM	lecessary	46.50 FL	*46.50 FL
9	1		*O/S FRONT DOOR	Bent	1,260.00 FL	*1,247.20 FL
10	1		*O/S REAR DOOR	Bent	1,248.00 FL	*1,248.00 FL
11	1		*O/S REAR FENDER INNER SHIELD	Serviceable	68.20 FL	*-FL
12	1		*O/S FRONT KNUCKLE ARM	Bent	628.20 FL	*521.50 FL
13	1		*O/S FRONT LOWER ARM	Distorted	732.50 FL	*543.90 FL
14	1		*O/S FRONT SHOCK ABSORBER	Bent	468.10 FL	*438.30 FL
15	1		*O/S FRONT STAY LINK	Serviceable	237.10 FL	*-FL
16	1		*WASHER TANK	Dented	146.90 FL	*146.90 FL
17	1		*O/S FRONT TYRE RIM	Dented	480.00 FS	*480.00 FS
F=Fra	anchise	part. S=SpcN	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	11,562.60	9,638.00
	- List Item Discount on L Items 25.00/25.00% (S\$)			2,770.65	2,289.50	
			т	otal Parts (S\$)	8,791.95	7,348.50
				_		

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	COMPUTERISE CHECK WHEEL ALIGNMENT	New	80.00	60.00
2	TO REMOVE & FIT O/S FRONT SUSPENSION	New	280.00	180.00
3	TO REMOVE & REFIT O/S FRONT & REAR DOORS GLASS & AUTO MECHANISM	New	120.00	120.00
4	TO REPAIR & PANEL BEAT O/S FRONT INNER PANEL,O/S ROCKER PANEL,O/S REAR FENDER,REAR BUMPER,DISMANTLE & FIT THE ABOVE PARTS	New	950.00	850.00
5	TO PUTTY & SPRAY PAINTING	New	1,480.00	1,200.00
	Gross Labou	r Cost (S\$)	2,910.00	2,410.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >