

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

## ESTIMATE OF REPAIR

Veh# : YN3746S

Model:

MIT FE83

Accident Date : 1/3/22

8-Apr-13

Location : SENOKO ROAD

3P:

SMJ7895G (EQ)

| S/Nos | Qty   | Description                                                                  | List \$ | S/Nett \$           | Nett \$  |
|-------|-------|------------------------------------------------------------------------------|---------|---------------------|----------|
| 1     | 1 pc  | Rear o/s pillar <i>Bent</i>                                                  |         | <del>800.00</del>   | 600(SN)  |
| 2     | 1 pc  | O/s box rear door panel <i>Dented</i>                                        |         | <del>1,500.00</del> | 1000(SN) |
| 3     | 1pc   | O/s box rear door panel hinges <i>New</i>                                    |         | 80.00               | +        |
| 4     | 1pc   | O/s box rear door panel lock middle <i>New</i>                               |         | 250.00              | +        |
| 5     | 1 pc  | N/s box rear door panel <i>2</i>                                             |         | 1,500.00            | +        |
| 6     | 1 pc  | N/s box rear door panel hinges <i>New</i>                                    |         | 80.00               | +        |
| 7     | 1pc   | N/s box rear door panel lock middle                                          |         | 250.00              | +        |
| 8     | 1 pc  | Rear tail-gate lower wooden cross member <i>Cracked</i>                      |         | <del>500.00</del>   | 300(SN)  |
| 9     | 1 pc  | Rear o/s tail-lamp bracket <i>Bent</i>                                       | 130.20  | ✓                   |          |
| 10    | 1 pc  | Rear o/s tail-lamp <i>cracked</i>                                            | 285.60  | ✓                   |          |
| 11    | 60pcs | Rivets <i>New</i>                                                            |         | <del>60.00</del>    | 40(SN)   |
| 12    | 1 pc  | Rear reg. no. plate <i>New</i>                                               |         | 45.00               | +        |
| 13    | 1 pc  | Rear LTA rear guard <i>Bent</i>                                              |         | <del>1,200.00</del> | 900(SN)  |
|       |       | <i>415.80 S.N: 2840</i> Sub-Total:                                           | 415.80  | 6,265.00            | 0.00     |
|       |       | <i>311.85</i>                                                                | 25%     | 0%                  | 0%       |
|       |       | After Less %:                                                                | 311.85  | 6,265.00            | 0.00     |
|       |       | <b>Labour</b>                                                                |         |                     |          |
| 1     |       | To repair front cabin panel dismantle, straighten and welding damage parts   |         | <del>1,400.00</del> | 700      |
| 2     |       | To spray painting                                                            |         | <del>500.00</del>   | 400      |
| 3     |       | To remove and refit rear carriage to facilitate changing wooden cross member |         | 300.00              | 5        |
| 4     |       | Provide lifting equipment to remove rear carriage)                           |         | <del>800.00</del>   | 400      |
| 5     |       | To check wiring                                                              |         | <del>120.00</del>   | 30       |
| 6     |       | To re-seal anti-rust <i>1580</i>                                             |         | <del>120.00</del>   | 50       |
|       |       | Sub-Total:                                                                   |         | 3,240.00            |          |
|       |       | <b>Total:</b>                                                                |         | 9,816.85            |          |
|       |       | After Less 20%:                                                              |         | 7,853.48            |          |

Chan San Choon

Director

DipEng, AAE MIMI,MSAE(Aust)



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: YN3746S ESTIMATEPg1

Date:

total: 473185  
H/S: 3.7K  
04 Days.

Mobil 1

