3/28/22, 11:02 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

CS/CTI22001971/UQY3N2 Our File No:

28/03/2022 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMPCSNW00259822100

Claimant Vehicle

FBK6947Y

Insured Vehicle

SCQ6866D

No:

No:

Claim

Date of Loss:

17/02/2022

Nature of Claim: TP

SNM22D201460/C02/CSC No:

DESCRIPTION & IDENTIFICATION OF VEHICLE

FBK6947Y Reg No:

HONDA CB400SF, 399cc Make & Model: Engine No: NC42E1202528 Reg. Date: 23/12/2015 (Man. Year: 2014) Chassis No: NC421602531 99556 km Colour: Blue Odometer:

Engine Capacity: 399 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes Nο

CONDITION OF TYRES

Front Tyre Size: 120/60ZR17 Rear Tyre Size: 160/60ZR17 Front Left Side: Rear Left Side: Bridgestone 6 mm Bridgestone 6 mm

Front Right Side: Rear Right Side: $0 \, \text{mm}$ 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		4,773.30	445.50	4,327.80	90.67
Miscellaneous Items		0.00	0.00	0.00	
Labour		400.00	120.00	280.00	70.00
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Nett Amount (S\$)	5.173.30	565.50	4.607.80	89.07

INSPECTION

Date of Assignment: 13/03/2022

Erofia Motor Trading Pte Ltd (KAKI BUKIT) Date Inspected: 09/03/2022 Inspected At:

1 KAKI BUKIT AVE 6 #02-62

Singapore 417883

Estimated Period of Repair: 1.0 days

Adjuster: MARCUS CHUA SHIAU CHAN Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 25 Mar 2022)

Parts: N/A HONDA CB400SF 399cc (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBK6947Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Repair	196.00 FL	*- FL
2	2		*FORK INNER TUBES	Not Necessary	1,020.00 FL	*- FL
3	2		*FORK OUTER TUBES	Serviceable	1,040.00 FL	*- FL
4	1		*FORK UNDER BRACKET	Not Necessary	335.00 FL	*- FL
5	1		*FORK OUTER COVER	Not Necessary	90.00 FL	*- FL
6	1		*FRONT SPORT RIM	Repair	1,100.00 FL	*- FL
7	1		*FRONT BRAKE DISCS	O/s Damaged	1,120.00 FL	*495.00 FL
8	1		*FRONT RIM SHAFT	Not Necessary	68.00 FL	*- FL
9	1		*FRONT RIM BEARING	Not Necessary	58.00 FL	*- FL
10	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
11	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
12	1		*STEERING CONE (1 SET)	Not Necessary	125.00 FS	*- FS
13	1		*NUMBER PLATE (1 SET)	Not Necessary	38.00 FS	*- FS
F=Fra	nchise p	oart. S=SpcNet	t. L=ListItemDisc.			
				Sub Total (S\$)	5,276.00	495.00
			- List Item Discoul	nt on L Items 10.00/10.00% (S\$)	502.70	49.50
				Total Parts (S\$)	4,773.30	445.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO PROVIDE TOWING SERVICE (LOD)	New	0.00	0.00
2	TO CHECK WIRING AND RESET HEADLAMP FORCUSING	New	80.00	0.00
3	TO PROVIDE LABOUR	New	320.00	120.00
	Gross	Labour Cost (S\$)	400.00	120.00
	Report was unsubmitted duri	ng this print-out.		

< END OF ESTIMATES >