

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EG122001976/AVY3E2

Date: 04/07/2022

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SJY1701D

Insured Vehicle No : GY5994J

Date of Loss: 28/02/2022

Nature of Claim:

TP

Claim No: CDMCG22000378

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJY1701D**

Make & Model: BMW 530I, 2.0 SE (A)

Engine No: 13339918

Reg. Date: 06/09/2017 (Man. Year: 2017)

Chassis No: WBAJA52090G885542

Colour: Black

Odometer: 79747 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45 R18

Rear Tyre Size: 245/45 R18

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,083.20	3,411.90	5,671.30	62.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,530.00	1,110.00	1,420.00	56.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,613.20	4,521.90	7,091.30	61.06
+ GST 7.00/7.00% (S\$)	812.92	316.53	496.39	61.06
Nett Amount (S\$)	12,426.12	4,838.43	7,587.69	61.06

INSPECTION

Date of Assignment: 02/03/2022

Date Inspected: 04/03/2022

Inspected At:

1st Autoworks Pte Ltd (HQ)

23 Kaki Bukit Ave 4, #04-01

Singapore 415933

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Jul 2022)
Parts:	143	BMW 530I 2.0 SE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJY1701D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT FENDER LH	Dented	1,850.00 FL	*985.00 FL
2	1		*FRT FENDER INNERSHIELD LH	Not Necessary	330.00 FL	*- FL
3	1		*FRT DOOR LH	Dented	3,590.00 FL	*2,387.00 FL
4	1		*FRT DOOR HINGE UPP LH	Not Necessary	200.00 FL	*- FL
5	1		*FRT DOOR HINGE LOW LH	Not Necessary	230.00 FL	*- FL
6	1		*FRT DOOR CHECKER LH - LINK CHECK	Not Necessary	330.00 FL	*- FL
7	1		*FRT DOOR LOCK LH	Not Necessary	390.00 FL	*- FL
8	1		*FRT DOOR LOCK CATCHER LH - STRIKER	Not Necessary	78.00 FL	*- FL
9	1		*FRT DOOR RUBBER BEADING LH - BODY SIDE	Necessary	460.00 FL	*245.00 FL
10	1		*FRT DOOR WEATHER STRIP LH	Necessary	495.00 FL	*174.00 FL
11	1		*FRT DOOR OUTER HANDLE LH	Not Necessary	495.00 FL	*- FL
12	1		*FRT DOOR OUTER HANDLE KNOB LH	Not Necessary	290.00 FL	*- FL
13	1		*FRT DOOR GLASS OUTER MLDG LH	Not Necessary	380.00 FL	*- FL
14	1		*FRT DOOR POWER WINDOW REGULATOR ASSY LH	Not Necessary	930.00 FL	*- FL
15	1		*SEALANT	Not Necessary	40.00 FS	*- FS
					Sub Total (S\$)	
					10,088.00	3,791.00
					- List Item Discount on L Items 10.00/10.00% (S\$)	
					1,004.80	379.10
					Total Parts (S\$)	
					9,083.20	3,411.90

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION, TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS. PER DAY \$ 650	New	1,500.00	500.00
2	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA. (LHF DOOR & FENDER,) PER PANEL	New	800.00	500.00
3	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	80.00	30.00
4	TRANSFER OF INTERNAL MECHANISM FROM OLD DOOR PANEL TO NEW DOOR PANEL	New	150.00	80.00
Gross Labour Cost (\$)			2,530.00	1,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >