

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22001979/KPA3Q2**Date:** 24/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070159670
Claimant Vehicle No :	SDF707R	Insured Vehicle No :	SMN8261H
Date of Loss:	01/03/2022	Nature of Claim:	TP
		Claim No:	3806789694SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDF707R	Engine No:	2ZR8041888
Make & Model:	TOYOTA C-HR HYBRID, 1.8 E G CVT (A)	Chassis No:	ZYX102015322
Reg. Date:	28/04/2017 (Man. Year: 2017)	Odometer:	52807 km
Colour:	Metallic Pearl White		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R18	Rear Tyre Size:	225/50 R18
Front Left Side:	Toyo 9 mm	Rear Left Side:	Toyo 9 mm
Front Right Side:	Toyo 9 mm	Rear Right Side:	Toyo 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,322.00	2,577.75	1,744.25	40.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,810.00	1,000.00	810.00	44.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	6,132.00	3,577.75	2,554.25	41.65
+ Loss of Use (5.0 x S\$80.00/day) (S\$)		400.00		
Nett Liability (S\$)		3,977.75		

INSPECTION

Date of Assignment:	02/03/2022	Jin Huat & Co (HQ)
Date Inspected:	02/03/2022 Inspected At:	176 SIN MING DRIVE #05-01, SIN MING
		AUTOCARE
		Singapore 575721
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled / Cracked	385.00 F	*385.00 FL
2	1		*LH FRONT FENDER	Buckled	325.00 F	*325.00 FL
3	1		*LH FRONT WHEEL ARCH GARNISH	Buckled	190.00 F	*190.00 FL
4	1		*LH FRONT SIDE RETAINER	Dented	59.00 F	*59.00 FL
5	1		*LH H/LAMP -HID	Cut	2,140.00 F	*2,140.00 FL
6	1		*LH H/LAMP BRACKET HOLDER	Distorted	85.00 F	*85.00 FL
7	1		*LH FRONT BUMPER SENSOR	Missing	235.00 F	*235.00 FL
8	1		*FRONT LOWER SPOILER	Serviceable	216.00 F	*- FL
9	1		*FRONT LOWER SIDE GRILLE COVER	Serviceable	65.00 F	*- FL
10	1		*FRONT BUMPER FOG LAMP	Serviceable	230.00 F	*- FL
11	1		*FRONT BUMPER REINFORCEMENT -TOP	Repair	216.00 F	*- FL
12	1		*FRONT BUMPER REINFORCEMENT -BOTTOM	Repair	158.00 F	*- FL
13	10		*CLIPS	Necessary	18.00 F	*18.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	4,322.00	3,437.00
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	859.25
Total Parts (\$)	4,322.00	2,577.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REPAIR AND REPLACE DAMAGED PARTS	New	850.00	400.00
2	CHECK WHEEL ALIGNMENT	New	60.00	0.00
3	SPRAY PAINTING AND UNDERSEAL (PEARL WHITE)	New	900.00	600.00
Gross Labour Cost (S\$)			1,810.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >