



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBR 7469S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HANDLE BAR	SERVICEABLE	320.00	-
1	SET HANDLE BAR GRIP	CUT	80.00	80.00
1	SET HANDLE BAR END	SERVICEABLE	188.00	-
1	SET HANDLE BAR KNOT	MISSING	120.00	35.00
1	SIDE MIRROR	DENTED	288.00	115.00
1	REAR FENDER	SERVICEABLE	99.00	-
1	REAR FENDER BACK COVER	CRACKED	252.00	210.00
1	SET REAR PLATE COVER	SERVICEABLE	88.00	-
1	REAR SIGNAL LAMP	CRACKED	226.00	88.00
1	LH FOOTREST BRACKET	BENT	334.00	178.00
1	REAR FENDER STAND	TO REPAIR SEE LABOUR	222.00	-
1	CLUTCH LEVER	SERVICEABLE	77.00	-
1	LH FOOTREST	SERVICEABLE	66.00	-
1	GEAR LEVER	SERVICEABLE	78.00	-
	LESS 10% DISCOUNT		-243.80	-70.60
			2,194.20	635.40
	<u>LABOUR</u>			
	TO PANEL BEATING / RESHAPE / STRAIGHTEN / DISMANTLE / RENEW / REPLACE THE ACCIDENT DAMAGED PORTION AND ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS. INCLUSIVE OF THE REPAIR OF REAR FENDER STAND.		450.00	100.00
	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY ON ACCIDENT DAMAGED AREA.		250.00	120.00
			700.00	220.00
	GRAND TOTAL		2,894.20	855.40
	RECOMMENDED COST OF REPAIRS			855.40

Report Ref No. CS/SMR22001986/Kvf3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.