

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001996/RVY3N2**Date:** 26/05/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00012742206

Claimant Vehicle No : SJM159P **Insured Vehicle No :** GZ2259M

Date of Loss: 27/02/2022 Nature of Claim: TP Claim No: SNM22D201435/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJM159P**

Make & Model: HONDA STREAM, 1.8 (A) Engine No: R18A1793025

Reg. Date: 18/12/2008 (Man. Year: 2008) Chassis No: RN61083869

Colour: White Odometer: 463424 km

Engine Capacity: 1799 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15

Front Left Side: APOLLO 6 mm Rear Left Side: APOLLO 6 mm

Front Right Side: APOLLO 6 mm Rear Right Side: APOLLO 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 2,659.61 | 1,911.68 | 747.93 | 28.12 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,300.00 | 1,020.00 | 1,280.00 | 55.65 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 4,959.61 | 2,931.68 | 2,027.93 | 40.89 |
| Approved Total (Overridden) (S\$) | | 2,350.00 | | |
| (S\$) | 4,959.61 | 2,350.00 | 2,609.61 | 52.62 |
| + GST 7.00/7.00% (S\$) | 347.17 | 164.50 | 182.67 | 52.62 |
| Nett Amount (S\$) | 5,306.78 | 2,514.50 | 2,792.28 | 52.62 |

INSPECTION

Date of Assignment: 07/03/2022

Date Inspected: 18/03/2022 Inspected At: Toh Ah Swee Spray Painting Co. (HQ)
60 Jalan Lam Huat, #07-33/34 Carros Centre
Singapore 737869

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|--|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 26 May 2022) |
| Parts: | M1-MPV | HONDA STREAM 1.8 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SJM159P) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|----------------------|---------------|-------------|--------------|
| 1 | 1 | | *BOOTLID | Bent | 1,208.08 FL | *1,045.90 FL |
| 2 | 1 | | *BUMPER | Deformed | 677.24 FL | *654.00 FL |
| 3 | 1 | | *BOOTLID COVER | Not Necessary | 295.09 FL | *- FL |
| 4 | 1 | | *END PANEL | Bent | 495.80 FL | *397.40 FL |
| 5 | 1 | | *REVERSE SENSOR | Cut | 160.00 FL | *160.00 FL |
| 6 | 1 | | *NO. PLATE | Not Necessary | 30.00 FL | *- FL |
| 7 | 1 | | *BOOTLID RUBBER SEAL | Necessary | 168.50 FL | *132.30 FL |
| 8 | 1 | | *BOOTLID INNER BOARD | Not Necessary | 289.80 FL | *- FL |

F=Franchise part. L=ListItemDisc.

| | | |
|--|-----------------|-----------------|
| Sub Total (\$\$) | 3,324.51 | 2,389.60 |
| - List Item Discount on L Items 20.00/20.00% (\$\$) | 664.90 | 477.92 |
| Total Parts (\$\$) | 2,659.61 | 1,911.68 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO REMOVE DAMAGED PARTS, TO KNOW OUT DENTS, TO STRAIGHTEN ADJUST, CHECK, RESHAPE INCLUDING CUTTING AND WELDING WHERE NECESSARY, TO REMOVE AND REINSTALL NECESSARY FITTINGS TO FACILITATE REPAIRS, TO REPLACE AND ALIGN THE ABOVE PARTS | New | 900.00 | 400.00 |
| 2 | PUTTY AND SPRAY PAINTING ON BODY AND ABOVE NEW REPAIRED PARTS INCLUDING SUPPLY OF PAINT MATERIAL | New | 900.00 | 500.00 |
| 3 | TO REMOVE AND REFIX REAR WINDSCREEN | New | 500.00 | 120.00 |
| Gross Labour Cost (\$\$) | | | 2,300.00 | 1,020.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >