

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001998/ATY3N2**Date:** 27/05/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00013232207

Claimant Vehicle No : GBJ7542E**Insured Vehicle No :** YN7180Y

Date of Loss: 01/03/2022

Nature of Claim: TP

Claim No: SNM22D201502/C02/CSC

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBJ7542E**

Make & Model: TOYOTA DYNA, 3.0 D (M)

Engine No: 1KD2860058

Reg. Date: 14/08/2019 (Man. Year: 2019)

Chassis No: JTFAT35Y70K213681

Colour: White

Odometer: 117394 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195R15C

Rear Tyre Size: 155R12C

Front Left Side: KAPSEN 6 mm

Rear Left Side: KAPSEN 6 mm

Front Right Side: KAPSEN 6 mm

Rear Right Side: KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,989.50	2,860.00	6,129.50	68.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,650.00	1,150.00	1,500.00	56.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,639.50	4,010.00	7,629.50	65.55
Approved Total (Overridden) (\$\$)		3,200.00		
Nett Amount (\$\$)	11,639.50	3,200.00	8,439.50	72.51

INSPECTION

Date of Assignment: 10/04/2022

Date Inspected: 30/03/2022 Inspected At:

JL Perfect Autowork Pte Ltd (HQ)
8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki
Bukit
Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 27 May 2022)	
Parts:	N/A	TOYOTA DYNA 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ7542E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL LAMP RH	Not Necessary	220.00 FL	*- FL
2	1		*TAIL LAMP SUPPORT BRACKET RH	Not Necessary	180.00 FL	*- FL
3	1		*REAR CARGO BED END PANEL	Not Necessary	1,426.00 FL	*- FL
4	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
5	1		*REAR BOX OPEN DOOR	Dented	2,800.00 FS	*1,700.00 FS
6	2		*REAR BOX OPEN DOOR HINGE	Not Necessary	240.00 FS	*- FS
7	1		*REAR BOX OPEN DOOR STAND HOLDER	Not Necessary	40.00 FS	*- FS
8	1		*REAR BOX OPEN DOOR LOCK CATCH	Not Necessary	120.00 FS	*- FS
9	1		*REAR BOX OPEN DOOR LOCK	Not Necessary	450.00 FS	*- FS
10	1		*REAR BOX COMPANY STICKER (SET)	Necessary	1,600.00 FS	*650.00 FS
11	1		*REAR BOX SIDE PILLAR RH	Repair	1,200.00 FS	*- FS
12	1		*REAR BOX SIDE PILLAR COVER RH	Dented	800.00 FS	*450.00 FS
13	1		*REAR BOX OPEN DOOR STICKER HEALTHIER CHOICE	Necessary	120.00 FS	*30.00 FS
14	1		*REAR BOX OPEN DOOR STICKER SYSTEM CERTIFICATION	Necessary	120.00 FS	*30.00 FS
15	1		*REAR CARGO BED END PANEL SEALANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	9,446.00	2,860.00
- List Item Discount on L Items 25.00/25.00% (S\$)	456.50	0.00
Total Parts (S\$)	8,989.50	2,860.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT, WELD, CUT, ADJUST, KNOCK	New	1,400.00	550.00
2	TO PUTTY, SPRAY PAINT, POLISH WAX	New	1,000.00	600.00
3	REAR CHASSIS ALIGNMENT	New	250.00	0.00
Gross Labour Cost (S\$)			2,650.00	1,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >