

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22002002/BVY3E2

Date: 11/05/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00181452100
Claimant Vehicle No: SJE6701B Insured Vehicle No: SNA7365E
Date of Loss: 02/03/2022 Nature of Claim: TP Claim No: SNM22D201523/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJE6701B
Make & Model: HONDA STREAM, 1.8 L RSZ (A) Engine No: R18A1767197
Reg. Date: 02/05/2008 (Man. Year: 2008) Chassis No: RN61060123
Colour: Grey Odometer: 226513 km
Engine Capacity: 1799 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
Front Left Side: Goodyear 5 mm Rear Left Side: Goodyear 5 mm
Front Right Side: Goodyear 5 mm Rear Right Side: Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,808.32	4,124.96	10,683.36	72.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,520.00	1,200.00	2,320.00	65.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	18,328.32	5,324.96	13,003.36	70.95
Approved Total (Overridden) (\$\$)		4,250.00		
(\$\$)	18,328.32	4,250.00	14,078.32	76.81
+ GST 7.00/7.00% (\$\$)	1,282.98	297.50	985.48	76.81
Nett Amount (\$\$)	19,611.30	4,547.50	15,063.80	76.81

INSPECTION

Date of Assignment: 08/03/2022
Date Inspected: 04/03/2022 Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
Singapore 415875
Estimated Period of Repair: 6.0 days

Adjuster: Lim Teow Guan

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 May 2022)
Parts:	M1-MPV	HONDA STREAM 1.8 L RSZ (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJE6701B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	683.90 FL	*683.90 FL
2	1		*BONNET LOCK	Not Damaged	56.80 FL	*- FL
3	1		*BONNET RUBBER SEAL	Not Damaged	101.30 FL	*- FL
4	1		*FRONT BUMPER	Broken	735.70 FL	*656.00 FL
5	1		*FRONT BUMPER RH SIDE RETAINER	Necessary	16.00 FL	*16.00 FL
6	1		*FRONT BUMPER LH SIDE RETAINER	Necessary	16.00 FL	*16.00 FL
7	1		*FRONT BUMPER RH FOG LAMP ASSY	Broken	255.00 FL	*255.00 FL
8	1		*FRONT BUMPER RH FOG LAMP COVER	Broken	109.90 FL	*65.70 FL
9	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 FL	*30.00 FL
10	1		*FRONT BUMPER REINFORCEMENT	Bent	218.80 FL	*185.00 FL
11	1		*FRONT BUMPER LOWER GRILLE	Not Damaged	82.10 FL	*- FL
12	1		*LH HEADLAMP ASSY	Not Damaged	880.40 FL	*- FL
13	1		*LH HEADLAMP LOWER BRACKET	Not Damaged	38.10 FL	*- FL
14	1		*RH HEADLAMP ASSY	Broken	880.40 FL	*697.50 FL
15	1		*RH HEADLAMP LOWER BRACKET	Broken	38.10 FL	*38.10 FL
16	1		*RH FRONT FENDER	Dented	486.20 FL	*486.20 FL
17	1		*RH FRONT FENDER BRACKET	Not Necessary	45.20 FL	*- FL
18	1		*RH FRONT SPLASH SHIELD	Torn	83.20 FL	*83.20 FL
19	1		*SET RH FRONT SPLASH SHIELD CLIPS	Necessary	40.00 FL	*30.00 FL
20	1		*RH FRONT FENDER VERTICAL SHIELD	No such part	68.00 FL	*- FL
21	1		*RH FRONT FENDER UPPER SIDE GARNISH	No such part	63.00 FL	*- FL
22	1		*FRONT GRILLE	Broken	335.40 FL	*238.10 FL
23	1		*FRONT GRILLE RSZ EMBLEM	Necessary	28.00 FL	*28.00 FL
24	1		*FRONT WIPER TANK	Not Damaged	89.20 FL	*- FL
25	1		*SUPPORT PANEL	Not Damaged	566.30 FL	*- FL
26	1		*SUPPORT PANEL TOP COVER	Not Damaged	127.70 FL	*- FL
27	1		*SET SUPPORT PANEL TOP COVER CLIPS	Not Damaged	45.00 FL	*- FL
28	1		*AIRCON CONDENSER	Not Damaged	1,008.00 FL	*- FL
29	1		*RADIATOR ASSY	Not Damaged	1,764.80 FL	*- FL
30	1		*RH FRONT LOWER ARM	Not Damaged	328.70 FL	*- FL
31	1		*RH FRONT SHOCK ABSORBER	Not Damaged	341.20 FL	*- FL
32	1		*RH FRONT SHOCK ABSORBER TOP MOUNTING	Not Damaged	73.00 FL	*- FL
33	1		*RH FRONT KNUCKLE ARM	Not Damaged	303.00 FL	*- FL
34	1		*RH FRONT WHEEL BEARING	Not Damaged	140.20 FL	*- FL
35	1		*RH FRONT TIE ROD END	Not Damaged	115.10 FL	*- FL
36	1		*RH FRONT DRIVE SHAFT	Not Damaged	1,033.20 FL	*- FL
37	1		*STEERING RACK AND PINION	Not Damaged	1,421.00 FL	*- FL
38	1		*FRONT BUMPER LOWER SPOILER	Broken	1,150.00 FS	*600.00 FS
39	1		*FRONT BUMPER UPPER RH CANARD	Broken	480.00 FS	*250.00 FS
40	1		*SET FRONT BUMPER UPPER RH CANARD RIVETS	Necessary	28.00 FS	*10.00 FS
41	1		*FRONT BUMPER LOWER RH CANARD	Broken	480.00 FS	*250.00 FS
42	1		*SET FRONT BUMPER LOWER RH CANARD RIVETS	Necessary	28.00 FS	*10.00 FS
43	1		*SET FRONT BUMPER RH SIDE RUBBER FASTENERS	Missing	420.00 FS	*150.00 FS
44	1		*RH FRONT SPORT RIM	Not Damaged	1,250.00 FS	*- FS
45	1		*RH FRONT TYRE	Not Damaged	450.00 FS	*- FS
46	1		*RH FRONT TYRE STICKER	Not Necessary	120.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*BRAKE FLUID	Not Necessary	55.00 FS	*- FS
48	1		*FRONT GRILLE RED EMBLEM	Necessary	85.00 FS	*48.00 FS
49	1		*SUPPORT PANEL JOINT SEALANT	Not Necessary	60.00 FS	*- FS
50	1		*FRONT NUMBER PLATE	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	17,343.90	4,826.70
- List Item Discount on L Items 20.00/20.00% (\$)	2,535.58	701.74
Total Parts (\$)	14,808.32	4,124.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE, CHECK, REPLACE AND REINSTALL DAMAGES BODYPARTS. TO PANEL BEATING, CUT/WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	1,200.00	600.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,200.00	600.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	100.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	100.00	0.00
5	REMOVE AND REPLACE AIRCON CONDENSER, PIPES AND HOSES TO ASSIST REPAIRS	New	220.00	0.00
6	REMOVE AND REPLACE RADIATOR ASSY, HOSES AND FAN ASSY	New	220.00	0.00
7	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS	New	380.00	0.00
8	TEST DRIVE AND ADJUST WHEEL ALIGNMENT SYSTEM	New	100.00	0.00
Gross Labour Cost (\$\$)			3,520.00	1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >