

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002004/UTY3N2**Date:** 05/04/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00041312100	
Claimant Vehicle No :	SLF9312S	Insured Vehicle No :	GBK8749P	
Date of Loss:	26/02/2022	Nature of Claim:	TP	Claim No: SNM22D201439/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF9312S		Engine No:	CAXF84884
Make & Model:	VOLKSWAGEN JETTA GP, 1.4 TSI 90 (A)		Chassis No:	WVWZZZ16ZGM030639
Reg. Date:	15/09/2016 (Man. Year: 2016)		Odometer:	224817 km
Colour:	Blue			
Engine Capacity:	1390 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Habilead 6 mm	Rear Left Side:	Habilead 6 mm
Front Right Side:	Habilead 6 mm	Rear Right Side:	Habilead 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,330.80	13,922.44	9,408.36	40.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,940.00	4,220.00	2,720.00	39.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	30,270.80	18,142.44	12,128.36	40.07
Approved Total (Overridden) (\$\$)		14,500.00		
Nett Amount (\$\$)	30,270.80	14,500.00	15,770.80	52.10

INSPECTION

Date of Assignment:	26/03/2022	
Date Inspected:	03/03/2022	Inspected At: Euro Success Services Pte Ltd (HQ) 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY Singapore 417883
Estimated Period of Repair:	15.0 days	

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Apr 2022)
Parts:	143	VOLKSWAGEN JETTA GP 1.4 TSI 90 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF9312S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR L/H	Badly Dented	1,963.45 FL	*1,963.45 FL
2	1		*FRONT DOOR INNER HANDLE L/H	Not Necessary	148.20 FL	*- FL
3	1		*FRONT DOOR INNER LOCK L/H	Jammed	357.30 FL	*357.30 FL
4	2		*FRONT DOOR HINGES L/H	Not Necessary	140.00 FL	*- FL
5	1		*FRONT DOOR PROTECTOR L/H	No such part	285.00 FL	*- FL
6	1		*FRONT DOOR INNER TRIM L/H	Deformed/Torn	980.00 FL	*980.00 FL
7	1		*FRONT DOOR INNER RUBBER L/H	Necessary	135.00 FL	*135.00 FL
8	1		*FRONT DOOR GLASS REGULATOR MOTOR LH	Jammed	310.70 FL	*310.70 FL
9	1		*FRONT DOOR LOCK ACTUATOR L/H	Jammed	395.80 FL	*395.80 FL
10	1		*FRONT DOOR OUTER HANDLE	Cut	120.60 FL	*120.60 FL
11	1		*FRONT DOOR WINDOW SWITCH	Not Necessary	384.90 FL	*- FL
12	1		*FRONT DOOR WINDOW REGULATOR	Bent/Jammed	485.70 FL	*436.95 FL
13	1		*FRONT DOOR GLASS MOULDING LH	Bent	195.60 FL	*161.00 FL
14	1		*FRONT DOOR WEATHER STRIP L/H	Repeated	215.40 FL	*- FL
15	1		*FRONT DOOR LOWER RUBBER SEAL	Necessary	85.10 FL	*85.10 FL
16	1		*FRONT DOOR FRAME BLACK COVER L/H	Necessary	75.00 FL	*75.00 FL
17	1		*FRONT DOOR FRAME WEATHERSTRIP L/H	Twisted	174.50 FL	*112.00 FL
18	2		*FRONT DOOR AUDIO SPEAKER L/H	Cracked	480.00 FL	*250.00 FL
19	1		*FRONT DOOR CENTRE LOCK L/H	No such part	268.20 FL	*- FL
20	1		*FRONT DOOR CENTRE PILLAR L/H	Badly Dented	1,210.40 FL	*650.00 FL
21	1		*FRONT WINDOW SEALANT L/H	Not Necessary	85.00 FL	*- FL
22	1		*FRONT WINDOW GLASS L/H	Pitted	620.40 FL	*415.00 FL
23	1		*FRONT WINDOW MOULDING L/H	Not Necessary	195.60 FL	*- FL
24	1		*CENTRE INNER PANEL LH	Badly Dented	825.30 FL	*645.00 FL
25	1		*ROCKER PANEL L/H	Badly Dented	1,320.80 FL	*855.00 FL
26	1		*REAR DOOR L/H	Distorted	1,670.10 FL	*1,670.10 FL
27	1		*REAR DOOR INNER HANDLE L/H	Cracked	121.40 FL	*121.40 FL
28	1		*REAR DOOR INNER LOCK L/H	Jammed	357.30 FL	*357.30 FL
29	2		*REAR DOOR HINGES L/H	Bent	140.00 FL	*140.00 FL
30	1		*REAR DOOR PROTECTOR LH	No such part	215.60 FL	*- FL
31	1		*REAR DOOR INNER TRIM L/H	Deformed/Torn	875.60 FL	*875.60 FL
32	1		*REAR DOOR INNER RUBBER L/H	Necessary	121.60 FL	*121.60 FL
33	1		*REAR DOOR LATCH ASSEMBLY L/H	Not Necessary	286.50 FL	*- FL
34	1		*REAR DOOR GLASS REGULATOR MOTOR LH	Jammed	354.50 FL	*354.50 FL
35	1		*REAR DOOR OUTER HANDLE	Cut	98.60 FL	*98.60 FL
36	1		*REAR DOOR WINDOW SWITCH	Not Necessary	345.50 FL	*- FL
37	1		*REAR DOOR WINDOW REGULATOR	Bent	456.30 FL	*436.95 FL
38	1		*REAR DOOR GLASS OUTER MOULDING LH	Distorted	191.00 FL	*112.00 FL
39	1		*REAR DOOR WEATHER STRIP L/H	Repeated	192.60 FL	*- FL
40	1		*REAR DOOR LOWER RUBBER SEAL	Necessary	85.10 FL	*85.10 FL
41	1		*REAR DOOR FRAME BLACK COVER L/H	Necessary	68.20 FL	*68.20 FL
42	1		*REAR DOOR FRAME WEATHER STRIP L/H	Twisted	176.60 FL	*176.60 FL
43	1		*REAR DOOR AUDIO SPEAKER L/H	Cracked	415.30 FL	*250.00 FL
44	1		*REAR DOOR CENTRE LOCK L/H	Not Necessary	230.90 FL	*- FL
45	1		*REAR WINDOW SEALANT L/H	Not Necessary	85.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*REAR WINDOW GLASS L/H	Shattered	620.40 FL	*415.00 FL
47	1		*REAR 1/4 WINDOW GLASS L/H	Not Necessary	195.60 FL	*- FL
48	1		*REAR WINDOW MOULDING L/H	Not Necessary	145.30 FL	*- FL
49	1		*REAR WINDSCREEN MOULDING	Necessary	90.20 FL	*90.20 FL
50	1		*REAR SEAT L/H	Serviceable	1,080.60 FL	*- FL
51	1		*REAR FENDER L/H	Badly Dented	2,100.00 FL	*1,615.00 FL
52	1		*REAR FENDER INNER TRIM L/H	Not Necessary	315.60 FL	*- FL
53	1		*REAR FENDER ARCH SEAL L/H	No such part	165.90 FL	*- FL
54	1		*REAR FENDER COWLING L/H	Not Necessary	124.60 FL	*- FL
55	1		*REAR ABSORBER L/H	Not Necessary	896.50 FL	*- FL
56	1		*REAR LOWER ARM L/H	Not Necessary	240.50 FL	*- FL
57	1		*REAR WHEEL BEARING L/H	Not Necessary	385.60 FL	*- FL
58	20		*FRONT & REAR TRIM BOARD CLIPS	Necessary	130.00 FS	*60.00 FS
59	10		*ROCKER PANEL LOWER GARNISH CLIPS	No such part	55.00 FS	*- FS
60	10		*REAR FENDER COWLING CLIPS	Not Necessary	50.00 FS	*- FS
61	10		*REAR FENDER INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
62	1		*REAR RIM L/H	Cut	850.00 FS	*380.00 FS
63	1		*REAR TYRE L/H	Not Necessary	200.00 FS	*- FS
64	1		*REAR WINDSCREEN SEALANT	Necessary	120.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	25,761.45	15,416.05
- List Item Discount on L Items 10.00/10.00% (\$)	2,430.65	1,493.61
Total Parts (\$)	23,330.80	13,922.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGES	New	120.00	0.00
2	TO KNOCK,PANEL BEAT,CUT,ADJUST ON DAMAGED AREA	New	2,500.00	2,400.00
3	RESPRAY PAINT ON DAMAGED AREA	New	2,200.00	1,300.00
4	TUFF COAT	New	200.00	120.00
5	TO REMOVE,REFIX CUSHION SEATS/ROOF LINING TO FACILIATE REPAIR	New	350.00	100.00
6	TO REMOVE & REFIX SPEAKERS & GARNISH & DOOR TRIM }	New	500.00	120.00
7	TO TRANSFER & REFIX FRONT AND REAR DOOR }	New	350.00	0.00
8	TO REMOVE AND REFIT UNDERCARRIAGE	New	350.00	0.00
9	CONDUCT FULL WHEEL ALIGNMENT	New	120.00	60.00
10	REMOVE & REFIX REAR WINDSCREEN	New	150.00	120.00
11	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
Gross Labour Cost (\$\$)			6,940.00	4,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >