

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22002005/KQY3E2**Date:** 14/11/2022REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: MSD/VMS/21-517208-WTT

Claimant Vehicle No : GBL6137M **Insured Vehicle No :** FBH6825G

Date of Loss: 22/02/2022 Nature of Claim: TP Claim No: MSC/V/22-000044

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBL6137M**

Make & Model: NISSAN NV350 CARAVAN, 2.0 DX (A) Engine No: QR20020160R

Reg. Date: 15/11/2021 (Man. Year: 2021) Chassis No: VR2E26136529

Colour: Grey Odometer: 13922 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/80 R15 Rear Tyre Size: 195/80 R15

Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 8 mm

Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,172.47	880.31	292.16	24.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,000.00	400.00	600.00	60.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	2,172.47	1,280.31	892.16	41.07
+ GST 7.00/7.00% (\$\$)	152.07	89.62	62.45	41.07
Nett Amount (\$\$)	2,324.54	1,369.93	954.61	41.07

INSPECTION

Date of Assignment: 03/03/2022

Date Inspected: 17/05/2022 Inspected At:

Cheng Hoe Motor Pte Ltd (AMK)
10 ANG MO KIO IND PARK 2A, #01-04 ANG MO KIO
AUTOPOINT
Singapore 568047

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 14 Nov 2022)	
Parts:	N/A	NISSAN NV350 CARAVAN 2.0 DX (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBL6137M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled / Dented	733.90 FL	*733.90 FL
2	5		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
3	1		*TAILGATE LOGO	Not Necessary	71.40 FL	*- FL
4	1		*TAILGATE EMBLEM CARAVAN	Not Necessary	110.00 FL	*- FL
5	1		*TAILGATE EMBLEM NV350	Not Necessary	121.00 FL	*- FL
6	1		*REVERSE SENSOR	Scratched	200.00 FS	*200.00 FS
7	1		*TAILGATE STICKER 70KM/HR	Not Necessary	10.00 FS	*- FS
8	1		*TAILGATE STICKER 8PAX	Not Necessary	10.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,278.30	955.90
- List Item Discount on L Items 10.00/10.00% (\$\$)	105.83	75.59
Total Parts (\$\$)	1,172.47	880.31

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX REAR BUMPER & ATTACHMENT;KNOCKING & REPAIR REAR END PANEL & REALIGN TAILGATE THE SAME	New	400.00	200.00
2	PUTTY & RESPRAY REAR BUMPER & PARKING SENSORS, TAILGATE, REAR END PANEL & ALL AFFECTED AREAS	New	600.00	200.00
Gross Labour Cost (\$\$)			1,000.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >