

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG122002008/AQY3N2**Date:** 15/06/2022REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SNA6956G **Insured Vehicle No :** XD3595A

Date of Loss: 12/02/2022 Nature of Claim: TP Claim No: CDMCG22000287

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNA6956G**

Make & Model: HONDA SHUTTLE HYBRID, 1.5 (A) Engine No: LEB6549182

Reg. Date: 20/04/2018 (Man. Year: 2018) Chassis No: GP71207459

Colour: Grey Odometer: 65647 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/50R16 Rear Tyre Size: 205/50R16

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,400.00	10,473.36	3,926.64	27.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,960.00	3,620.00	1,340.00	27.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,360.00	14,093.36	5,266.64	27.20
Approved Total (Overridden) (S\$)		11,250.00		
(S\$)	19,360.00	11,250.00	8,110.00	41.89
+ GST 7.00/7.00% (S\$)	1,355.20	787.50	567.70	41.89
Nett Amount (S\$)	20,715.20	12,037.50	8,677.70	41.89

INSPECTION

Date of Assignment: 03/03/2022

Date Inspected: 03/03/2022 Inspected At: Modern Automotive Pte Ltd (HQ)
Blk 3023A Ubi Road 1, #01-61 & #01-58
Singapore 408717

Estimated Period of Repair: 9.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 14 Jun 2022)	
Parts:	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNA6956G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	988.60 FL	*988.60 FL
2	2		*REAR BUMPER SIDE HOLDER-LH & RH	Necessary	64.00 FL	*64.00 FL
3	2		*REAR BUMPER SIDE SPONGE-LH & RH	Cracked	94.40 FL	*94.40 FL
4	2		*REAR BUMPER SIDE GRILLE-LH & RH	Deformed	90.80 FL	*90.80 FL
5	2		*REAR BUMPER SIDE GRILLE REFLECTOR-LH & RH	Not Necessary	90.40 FL	*- FL
6	1		*REAR END PANEL	Dented	681.20 FL	*681.20 FL
7	1		*REAR END PANEL TOP GARNISH	Deformed	168.90 FL	*168.90 FL
8	2		*TAILLAMP-LH & RH	Cracked	1,041.00 FL	*1,041.00 FL
9	2		*TAILLAMP PANEL-LH & RH	Dented	536.40 FL	*536.40 FL
10	1		*TAILGATE	Distorted	1,193.20 FL	*1,193.20 FL
11	1		*TAILGATE LOCK	Jammed	298.40 FL	*298.40 FL
12	1		*TAILGATE WEATHERSTRIPE	Cut	168.50 FL	*168.50 FL
13	1		*TAILGATE OUTER GARNISH	Deformed	383.80 FL	*383.80 FL
14	2		*TAILGATE REFLECTOR-LH & RH	Cut	761.80 FL	*761.80 FL
15	1		*TAILGATE INNER TRIMBOARD	Deformed	320.40 FL	*320.40 FL
16	1		*TAILGATE GLASS	Shattered	1,210.10 FL	*1,210.10 FL
17	1		*TAILGATE GLASS MOULDING	Necessary	149.20 FL	*149.20 FL
18	2		*TAILGATE DAMPER-LH & RH	Not Necessary	336.40 FL	*- FL
19	1		*TAILGATE WIPER ARM	Cut	95.50 FL	*95.50 FL
20	1		*TAILGATE WIPER ARM COVER	Missing	15.90 FL	*15.90 FL
21	1		*TAILGATE WIPER BLADE	Cut	66.50 FL	*66.50 FL
22	1		*TAILGATE WIPER MOTOR	Damaged	428.20 FL	*428.20 FL
23	1		*HONDA LOGO	Necessary	81.30 FL	*81.30 FL
24	1		*SHUTTLE EMBLEM	Necessary	65.10 FL	*65.10 FL
25	1		*HYBRID EMBLEM	Necessary	58.70 FL	*58.70 FL
26	2		*REAR FENDER-LH & RH	Repair	2,021.80 FL	*- FL
27	2		*REAR FENDER INNER SHIELD-LH & RH	Not Necessary	221.00 FL	*- FL
28	2		*REAR FENDER INNER TRIMBOARD-LH & RH	Deformed	799.20 FL	*799.20 FL
29	2		*REAR FENDER INNER TRIMBOARD UPPER-LH & RH	Not Necessary	596.20 FL	*- FL
30	1		*SPARE TYRE PANEL	Repair	1,180.00 FL	*- FL
31	1		*SPARE TYRE PANEL TOP BOARD	Deformed	585.20 FL	*585.20 FL
32	1		*SPARE TYRE PANEL UTILITY TRAY	Deformed	495.00 FL	*495.00 FL
33	1		*TOOLS TRAY SPONGE	Cracked	225.40 FL	*225.40 FL
34	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
35	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
36	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
37	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
38	1		*SET TAILGATE OUTER GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
39	1		*SET TAILGATE INNER TRIMBOARD CLIPS	Necessary	30.00 FS	*30.00 FS
40	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
41	1		*TAILGATE GLASS SOLAR FILM	Necessary	280.00 FS	*220.00 FS
42	1		*REAR CAMERA	Damaged	450.00 FS	*380.00 FS
43	1		*VIDEO RECORDER	Damaged	550.00 FS	*480.00 FS
44	1		*SET REAR FENDER INNER SHIELD CLIPS	Not Necessary	40.00 FS	*- FS
45	1		*SET REAR FENDER INNER TRIMBOARD CLIPS	Necessary	60.00 FS	*60.00 FS
46	1		*SET REAR FENDER INNER TRIMBOARD UPPER CLIPS	Not Necessary	50.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR NUMBER PLATE	Deformed	30.00 FS	*30.00 FS
48	1		*REAR NUMBER PLATE HOLDER	Deformed	30.00 FS	*30.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					17,502.50	12,686.70
- List Item Discount on L Items 20.00/20.00% (\$)					3,102.50	2,213.34
Total Parts (\$)					14,400.00	10,473.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS	New	2,000.00	1,500.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	1,800.00	1,400.00
3	TO CHECK WIRING SYSTEM	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE REAR CAMERA	New	100.00	50.00
6	TO REMOVE VIDEO RECORDER	New	100.00	50.00
7	TO SPRAY TUFF COAT	New	150.00	120.00
8	TO REMOVE UPHOLSTERY	New	150.00	80.00
9	TO REPLACE TAILGATE GLASS	New	180.00	120.00
10	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
11	TO VACUUM AND CLEAN UP GLASS FRAGMENTS	New	120.00	80.00
12	TOWING FEES	New	60.00	60.00
Gross Labour Cost (\$\$)			4,960.00	3,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >