

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002009/TQY3Q2**Date:** 15/11/2022REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00073982100

**Claimant Vehicle
No :** SJM9337H**Insured Vehicle
No :** GBC8001E

Date of Loss: 22/02/2022

Nature of Claim: TP

Claim
No: SNM22D201392/C02/THAMYLDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJM9337H**

Make & Model: MERCEDES-BENZ CLC180, 1.8 Kompressor (A)

Engine No: HIDDEN

Reg. Date: 01/01/2009 (Man. Year: 2009)

Chassis No: WDB2037462E053635

Colour: Black

Odometer: 207646 km

Engine Capacity: 1796 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40 R18

Rear Tyre Size: 225/40 R18

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,821.80	6,425.80	13,396.00	67.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,300.00	1,220.00	3,080.00	71.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,121.80	7,645.80	16,476.00	68.30
Approved Total (Overridden) (S\$)		6,100.00		
Nett Amount (S\$)	24,121.80	6,100.00	18,021.80	74.71

INSPECTION

Date of Assignment: 11/11/2022

Date Inspected: 03/03/2022 Inspected At:

Blk 1 Kaki Bukit Avenue 6 #01-08 Autobay
Repairer: Tsl Auto Garage (HQ)

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Nov 2022)

Parts: M1-COUPE MERCEDES-BENZ CLC180 1.8 Kompressor (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJM9337H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH FRONT FENDER	Bent	697.00 FL	*554.00 FL
2	1		*RH FRONT FENDER INNER COWLING	Not Necessary	254.00 FL	*- FL
3	1		*RH FRONT FENDER PROTECTOR	Missing	68.00 FL	*68.00 FL
4	1		*RH FRONT DOOR	Bent	1,985.00 FL	*1,750.00 FL
5	1		*RH FRONT DOOR PROTECTOR	Cut	221.00 FL	*221.00 FL
6	1		*RH FRONT DOOR GLASS OUTER MOULDING	Not Necessary	242.00 FL	*- FL
7	2		*RH FRONT DOOR HINGE	Not Necessary	220.00 FL	*- FL
8	1		*RH FRONT DOOR CHECKER	Not Necessary	98.00 FL	*- FL
9	1		*RH FRONT DOOR LOCK WITH SENSOR	Not Necessary	341.00 FL	*- FL
10	1		*RH FRONT DOOR LOCK WITH SENSOR COVER	Not Necessary	145.00 FL	*- FL
11	1		*RH FRONT DOOR INNER TRIM BOARD	Not Necessary	1,264.00 FL	*- FL
12	1		*RH FRONT DOOR WEATHERSTRIPE	Necessary	289.00 FL	*289.00 FL
13	1		*RH FRONT DOOR POWER WINDOW MOTOR	Not Necessary	761.00 FL	*- FL
14	1		*RH FRONT DOOR POWER WINDOW GEAR	Not Necessary	364.00 FL	*- FL
15	1		*RH FRONT DOOR MIRROR	Broken	1,652.00 FL	*1,020.00 FL
16	1		*RH FRONT DOOR MIRROR COVER	Cracked	126.00 FL	*126.00 FL
17	1		*RH ROCKER PANEL GARNISH	Cracked	1,189.00 FL	*979.00 FL
18	1		*RH FRONT SHOCK ABSORBER	Not Necessary	672.00 FL	*- FL
19	1		*RH FRONT KNUCKLE ARM	Not Necessary	689.00 FL	*- FL
20	1		*RH FRONT LOWER ARM (FRONTAL)	Not Necessary	774.00 FL	*- FL
21	1		*RH FRONT LOWER ARM (REAR)	Not Necessary	699.00 FL	*- FL
22	1		*RH FRONT UPPER ARM	Not Necessary	696.00 FL	*- FL
23	1		*RH FRONT WHEEL BEARING WITH HUB	Not Necessary	460.00 FL	*- FL
24	1		*RH FRONT STABILIZER LINKAGE	Not Necessary	168.00 FL	*- FL
25	1		*FRONT STEERING RACK & PINION	Not Necessary	5,673.00 FL	*- FL
26	1		*FRONT BUMPER	Torn	1,105.00 FL	*1,105.00 FL
27	1		*FRT RH WHEEL RIM	Cut	950.00 FL	*950.00 FL
28	1		*RH FRONT FENDER INNER COWLING CLIPS	Necessary	60.00 FS	*20.00 FS
29	1		*RH ROCKER PANEL GARNISH CLIPS	Necessary	80.00 FS	*30.00 FS
30	1		*RH FRONT DOOR PROTECTOR CLIPS	Necessary	60.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	22,002.00	7,132.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,180.20	706.20
Total Parts (\$\$)	19,821.80	6,425.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING	New	1,800.00	500.00
2	LABOUR FOR SPRAY PAINTING	New	1,400.00	600.00
3	LABOUR FOR REMOVE & TRANSFER RH FRONT DOOR FITTING	New	150.00	60.00
4	TO APPLY TUFF COAT /RUST PROOF ON ACCIDENT AREAS	New	300.00	30.00
5	WIRING CHECK	New	80.00	30.00
6	TEST FOR WATER LEAKING	New	120.00	0.00
7	LABOUR FOR REMOVE & RENEW RH FRONT UNDER CARRIAGE	New	300.00	0.00
8	TO CONDUCT WHEEL ALIGNMENT	New	150.00	0.00
Gross Labour Cost (S\$)			4,300.00	1,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >