



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2203833

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 20/06/2022
Reference CC6/CTI22002017/Apa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SMC 9657B
Insured Veh. GZ 2054L
Claim No. SNM22D201547/C02
Policy No. DMCVSNA00004752201
Accident Date 01/03/2022
Inspection Date 02/03/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Ref: CC6/CTI22002017/Apa3q2 Date: 20/06/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GZ 2054L	Veh. Inspected	SMC 9657B	
Policy No.	DMCVSNA00004752201	Coverage (\$)	0.00	
Claim No.	SNM22D201547/C02	Excess (\$)	0.00	
Assign From		Assign Date	02/03/2022	
2. Vehicle Particulars & Condition				
Make & Model	KIA SORENTO	c.c	2199	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	KNAPH81BMJ5465517	Colour	BRONZE	
Odometer	74533 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/60 R18	YOKOHAMA	6 mm	
L/H Front Tyre	235/60 R18	YOKOHAMA	6 mm	
R/H Rear Tyre	235/60 R18	YOKOHAMA	6 mm	
L/H Rear Tyre	235/60 R18	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/03/2022	Inspection Date	02/03/2022	
Survey held at	YSK AUTO WORKSHOP 1 KAKI BUKIT AVE 6 @ AUTOBAY #01-71 SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMC 9657B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DISTORTED	605.90	605.90
1	REAR BUMPER TOW COVER	DEFORMED	24.10	24.10
2	REAR BUMPER SIDE HOLDER @\$30.40	O/S DAMAGED	60.80	30.40
2	REAR BUMPER REFLECTOR @\$129.90	O/S CRACKED	259.80	129.90
2	REAR BUMPER REFLECTOR GRILLE @\$68.00	O/S CRACKED	136.00	68.00
1	REAR BUMPER LOWER GARNISH (BLACK)	DISTORTED	565.40	565.40
1	REAR BUMPER LOWER DIFFUSER (GREY)	DISTORTED	194.20	194.20
1	REAR BUMPER REINFORCEMENT	DENTED	359.40	359.40
4	REVERSE SENSOR @\$205.00	DAMAGED (2 PCS ONLY)	820.00	410.00
4	REVERSE SENSOR HOLDER @\$18.00	NECESSARY	72.00	72.00
1	REVERSE SENSOR WIRE HARNESS	NOT NECESSARY	358.40	-
1	REAR END PANEL	DENTED	681.50	681.50
1	REAR END PANEL TOP GARNISH	CRACKED	188.30	188.30
2	TAILLAMP @\$751.00	O/S CRACKED / N/S CUT	1,502.00	1,502.00
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	294.10	-
1	TAILGATE	DISTORTED	1,445.50	1,445.50
1	TAILGATE LOCK	DAMAGED	652.40	652.40
1	TAILGATE WEATHERSTRIPE	CUT	185.40	185.40
2	TAILGATE REFLECTOR @\$493.10	O/S CRACKED / N/S CUT	986.20	986.20
2	TAILGATE AUTO DAMPER @\$874.00	NOT NECESSARY	1,748.00	-
1	TAILGATE INNER TRIM BOARD	CUT	425.80	425.80
1	TALGATE GLASS	SHATTERED	894.90	894.90
1	TALGATE GLASS MOULDING	NECESSARY	135.90	135.90
1	TAILGATE WIPER MOTOR	DAMAGED	398.40	398.40
1	TAILGATE WIPER ARM	CRACKED	98.50	98.50
2	TAILGATE INNER SIDE TRIM @\$201.00	NOT NECESSARY	402.00	-
1	KIA LOGO	NECESSARY	69.20	69.20
1	SORENTO WORDING	NECESSARY	38.40	38.40



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	CYCLE CARRIAGE LOGO	NECESSARY	35.90	35.90
1	ECO DYNOMIC EMBLEM	NECESSARY	42.90	42.90
1	FLOOR PANEL TOP BOARD	NOT NECESSARY	349.80	-
1	UTILITY TOOLS BOX	CRACKED	324.90	324.90
1	REAR EXHAUST PIPE	BENT	1,177.10	1,177.10
1	REAR EXHAUST PIPE MOUNTING	NOT NECESSARY	35.40	-
1	REAR EXHAUST PIPE GASKET	NECESSARY	30.40	30.40
2	REAR FENDER INNER TRIM BOARD @\$552.00	NOT NECESSARY	1,104.00	-
	LESS 10% DISCOUNT		-	-1,177.29
			16,702.90	10,595.61
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	30.00	-
1	REAR NUMBER PLATE HOLDER (SN)	NOT NECESSARY	30.00	-
1	REAR BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	20.00	20.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	60.00	60.00
1	TAILGATE INNER TRIM BOARD CLIPS (SN)	NECESSARY	30.00	30.00
1	TALGATE GLASS SEALANT (SN)	NECESSARY	60.00	60.00
1	TALGATE GLASS SOLAR FILM (SN)	NECESSARY	280.00	200.00
1	REAR VIDEO RECORDER (SN)	MISSING	480.00	380.00
1	REAR FENDER INNER TRIM CLIPS (SN)	NOT NECESSARY	60.00	-
			1,100.00	780.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF TAILLAMP PANEL RH .		1,200.00	900.00
	SPRAY PAINTING .		1,200.00	800.00
	WIRING.		50.00	30.00
	TO REMOVE REVERSE SENSOR .		100.00	60.00
	TO SPRAY TUFF COAT.		150.00	60.00
	TO REMOVE UPHOLSTERY .		150.00	60.00
	TO TRANSFER TAILGATE FITTINGS.		150.00	60.00
	TO REPLACE TAILGATE GLASS .		180.00	120.00
	TO REPLACE VIDEO RECORDER .		100.00	50.00

Report Ref No. CC6/CTI22002017/Apa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE EXHAUST PIPE.		150.00	80.00
	TO VACUUM AND CLEAN UP GLASS SPLINTERS .		150.00	60.00
			3,580.00	2,280.00
GRAND TOTAL			21,382.90	13,655.61
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				10,900.00

Report Ref No. CC6/CTI22002017/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMC 9657B

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMC 9657B

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMC 9657B

RE-INSPECTION

