

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22002018/AVCE2

Date: 27/06/2022

REFERENCE

Insured/Claimant:	CAROLYN JOYCE TIEMANN	Policy No:	7210046972	
Date of Loss:	28/02/2022	Nature of Claim:	OD	Claim No: 4889095283SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMZ7820M		
Make & Model:	AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17) (A)	Engine No:	CZDC39824
Reg. Date:	18/05/2021 (Man. Year: 2021)	Chassis No:	WAUZZZF31M1117022
Colour:	Black	Odometer:	9626 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$172,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65 R17	Rear Tyre Size:	215/65 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,566.00	4,937.20	10,628.80	68.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	20,532.00	4,362.00	16,170.00	78.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	36,098.00	9,299.20	26,798.80	74.24
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	35,298.00	8,499.20	26,798.80	75.92
+ GST 7.00/7.00% (S\$)	2,470.86	594.94	1,875.92	75.92
Nett Amount (S\$)	37,768.86	9,094.14	28,674.72	75.92

INSPECTION

Date of Assignment:	03/03/2022		
Date Inspected:	03/03/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	6.0 days		

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,738.00 FS	*- FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	220.00 FS	*- FS
3	1		*REAR BUMPER SPOILER	Cut	510.00 FS	*408.00 FS
4	1		*REAR BUMPER BRACKET	Not Necessary	53.00 FS	*- FS
5	1		*REAR LIGHT REFLECTOR - LH	Not Necessary	46.00 FS	*- FS
6	1		*REAR BUMPER GUIDE SECTION - LH	Not Necessary	71.00 FS	*- FS
7	2		*REAR WHEEL ARCH COVER - LH / RH	N/S Missing / O/S Necessary	566.00 FS	*452.00 FS
8	1		*REAR FENDER - LH	Repair	3,640.00 FS	*- FS
9	1		*QUARTER WINDOW - LH	Not Necessary	683.00 FS	*- FS
10	1		*PRIMER	Not Necessary	22.00 FS	*- FS
11	1		*REAR END PANEL	Not Necessary	329.00 FS	*- FS
12	1		*REAR WHEEL HOUSING LINER	Not Necessary	262.00 FS	*- FS
13	1		*REAR WHEEL SPOILER - LH	Not Necessary	44.00 FS	*- FS
14	1		*REAR DOOR - LH	Distorted	3,127.00 FS	*2,501.60 FS
15	1		*REAR DOOR OUTER SEAL - LH	Necessary	151.00 FS	*120.40 FS
16	1		*REAR DOOR CATCH - LH	Damaged	120.00 FS	*96.00 FS
17	1		*REAR SILL PANEL SEAL - LH	Not Necessary	151.00 FS	*- FS
18	1		*REAR DOOR COVER - LH	Cut	270.00 FS	*216.00 FS
19	1		*REAR DOOR HANDLE - LH	Repair	222.00 FS	*- FS
20	1		*REAR DOOR HOUSING - LH	Not Necessary	31.00 FS	*- FS
21	1		*REAR DOOR WINDOW REGULATOR - LH	Not Necessary	302.00 FS	*- FS
22	1		*REAR DOOR WINDOW MOTOR - LH	Not Necessary	299.00 FS	*- FS
23	1		*ALUMINIUM RIM	Cut	1,414.00 FS	*1,131.20 FS
24	4		*RUBBER VALVE	Not Necessary	15.00 FS	*- FS
25	1		*1/4 GLASS SEALANT	Not Necessary	100.00 FS	*- FS
26	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
27	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
28	1		*ARYLIC SEALANT	Not Necessary	180.00 FS	*- FS
29	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
30	1		*SUNDRIES	Necessary	400.00 FS	*12.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 15,566.00 4,937.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND RENEW REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
2	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	400.00	280.00
3	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,400.00	0.00
4	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	0.00
5	TO REMOVE AND RENEW LHS 1/4 GLASS TO FACILITATE RENEWAL OF LHS REAR FENDER	New	300.00	0.00
6	TO INSTALL SOLAR FILM FOR LHS 1/4 GLASS	New	400.00	0.00
7	TO DISMANTLE AND RENEW REAR BUMPER AND LHS REAR DOOR. TO CUT OUT AND WELD REAR FENDER AND REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	8,800.00	1,500.00
8	TO RESPRAY REAR BUMPER, LHS REAR FENDER, LHS REAR DOOR, DOOR HANDLE, LHS SILL PANEL, ROOF CHANNEL, DRAIN CHANNEL, DOOR ENTRANCES AND REAR END PANELLING	New	7,000.00	1,750.00
9	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
10	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			20,532.00	4,362.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >