

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22002019/RPA3Q2**Date:** 18/10/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070149693
Claimant Vehicle No :	SHB5913C	Insured Vehicle No :	GBK6000D
Date of Loss:	01/03/2022	Nature of Claim:	TP
		Claim No:	4321756407SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB5913C		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2F14420
Reg. Date:	12/12/2019 (Man. Year: 2019)	Chassis No:	JTDKB3FU303088829
Colour:	Maroon	Odometer:	227174 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 6 mm	Rear Left Side:	Sailun 6 mm
Front Right Side:	Sailun 6 mm	Rear Right Side:	Sailun 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,068.80	743.03	2,325.77	75.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,614.00	440.00	1,174.00	72.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	4,682.80	1,183.03	3,499.77	74.74
+ Car Rental (3.0 x S\$73.00/day) (S\$)		219.00		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		1,409.03		
Global Sum Settlement (S\$)		1,400.00		

INSPECTION

Date of Assignment:	03/03/2022	
Date Inspected:	03/03/2022 Inspected At:	Strides Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	2.0 days	

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*GUARD ,RR BUMPER ,LOWER (DISC 25%)	Scratched	374.50 F	*280.88 F
2	1		*CLIPS PIECE ,FRT & RR BUMPER (DISC 25%) (10 PCS)	Necessary	45.00 F	*33.75 F
3	1		*COVER ,RR BUMPER ASSY (DISC 25%)	Deformed	485.60 F	*364.20 F
4	1		*PAD ,RR BUMPER ,CTR (DISC 25%) (3 PCS)	Necessary	33.00 F	*24.75 F
5	2		*PAD ,RR BUMPER RH & LH 3 (DISC 25%)	Necessary	22.00 F	*16.50 F
6	2		*PAD ,RR BUMPER RH & LH 2 (DISC 25%)	Necessary	8.00 F	*6.00 F
7	1		*SEAL ,RR BUMPER ARM ,RH & LH (DISC 25%) (2 PCS)	Necessary	22.60 F	*16.95 F
8	1		*SENSOR REVERSE	Not Necessary	180.00 F	*- F
9	1		*REAR BUMPER REFLECTOR ASSY ,REFLEX LH	Not Necessary	39.00 F	*- F
10	1		*COVER ,GUARD ,RR BUMPER LOWER	Not Necessary	22.00 F	*- F
11	1		*SEAL ,RR BUMPER ,RH	Not Necessary	118.30 F	*- F
12	2		*STOPPER ,RR BUMPER ,RH & LH	Not Necessary	4.50 F	*- F
13	1		*RETAINER ,RR BUMPER RH	Not Necessary	132.60 F	*- F
14	1		*RETAINER ,RR BUMPER LH	Not Necessary	132.60 F	*- F
15	1		*ANTENNA ELECTRICAL KEY	Not Necessary	72.00 F	*- F
16	1		*END PANEL SUB-ASSY BODY LOWER BACK	Not Necessary	651.00 F	*- F
17	1		*SEAL ,RR BUMPER ,LH	Not Necessary	118.30 F	*- F
18	1		*REAR BUMPER GROMMET SCREW	Not Necessary	2.20 F	*- F
19	1		*REAR BUMPER REFLECTOR ASSY ,REFLEX RH	Not Necessary	39.00 F	*- F
20	1		*COVER ,REAR FLOOR UNDER CENTER	Not Necessary	229.90 F	*- F
21	1		*COVER ,RR BUMPER ASSY	Not Necessary	332.70 F	*- F
22	2		*PAD ,RR BUMPER ,RH & LH 1	Not Necessary	4.00 F	*- F

F=Franchise part.

Total Parts (S\$)	3,068.80	743.03
--------------------------	-----------------	---------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODYWORK	New	676.00	200.00
2	SPRAY PAINT	New	558.00	200.00
3	TO WASH AND VACUUM	New	60.00	0.00
4	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	0.00
5	TO REPLACE SUNDRY PARTS	New	100.00	0.00
6	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	40.00
Gross Labour Cost (\$)			1,614.00	440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >