

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22002021/KPA3Q2**Date:** 06/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100351379
Claimant Vehicle No :	SGD6886S	Insured Vehicle No :	SKK9039S
Date of Loss:	28/02/2022	Nature of Claim:	TP
		Claim No:	2448441455SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGD6886S	Engine No:	3ZRB815413
Make & Model:	TOYOTA HARRIER, 2.0 (A)	Chassis No:	ZSU600082276
Reg. Date:	03/05/2017 (Man. Year: 2016)	Odometer:	95844 km
Colour:	Metallic Maroon		
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/65 R17	Rear Tyre Size:	225/65 R17
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,823.95	3,704.35	1,119.60	23.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,730.00	1,310.00	420.00	24.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,553.95	5,014.35	1,539.60	23.49
Approved Total (Overridden) (S\$)		4,000.00		
(S\$)	6,553.95	4,000.00	2,553.95	38.97
+ GST 7.00/7.00% (S\$)	458.78	280.00	178.78	38.97
Nett Amount (S\$)	7,012.73	4,280.00	2,732.73	38.97
+ Car Rental (7.0 x S\$150.00/day) (S\$)		1,050.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,332.00		

INSPECTION

Date of Assignment:	02/03/2022	
Date Inspected:	02/03/2022	Inspected At: Alan's United Auto Pte Ltd (HQ) Blk 7 Sin Ming Industrial Estate, #01-76 Singapore 575642
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Bent	1,369.50 FL	*1,369.50 FL
2	1		*TAIL GATE INNER LOCK	Dented	571.10 FL	*571.10 FL
3	1		*TAIL GATE RUBBER	Dented / Distorted	410.40 FL	*341.60 FL
4	2		*TAIL GATE GLASS MOULDING	Necessary	61.00 FL	*61.00 FL
5	1		*TAIL GATE GLASS MOULDING (LOW)	Necessary	50.70 FL	*50.70 FL
6	1		*TAIL GATE HARRIER EMBLEM	Necessary	62.20 FL	*62.20 FL
7	1		*REAR BUMPER FASCIA	Buckled	1,395.10 FL	*1,381.00 FL
8	1		*REAR BUMPER LOWER SPOILER	Dented / Cut	586.30 FL	*586.30 FL
9	1		*REAR BUMPER SPONGE	Cracked	142.40 FL	*142.40 FL
10	2		*REAR BUMPER SPOILER REFLECTOR	Serviceable	109.00 FL	*- FL
11	1		*REAR END PANEL	Repair	715.50 FL	*- FL
12	1		*END PANEL TOP GARNISH	Serviceable	425.40 FL	*- FL
13	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	300.00 FS	*200.00 FS
14	1		*SET REAR BUMPER CLIP	Necessary	40.00 FS	*40.00 FS
15	1		*REAR W/S GLASS SEALANT	Necessary	60.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,298.60	4,845.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,474.65	1,141.45
Total Parts (\$\$)	4,823.95	3,704.35

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIX REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	150.00	120.00
2	TO REMOVE ROOF LINING FRONT AND REAR SEATS ,TRIM BOARD AND CARPET	New	120.00	60.00
3	TO APPLY UNDERSEALING	New	60.00	30.00
4	TO PUTTY AND SPRAY REPLACED PARTS	New	700.00	600.00
5	TO REMOVE ,CUT -OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ABOVE PARTS	New	700.00	500.00
Gross Labour Cost (\$)			1,730.00	1,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >