

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22002025/UPA3Q2**Date:** 23/06/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700033853
Claimant Vehicle No :	PC1179G	Insured Vehicle No :	SLS2328A
Date of Loss:	01/03/2022	Nature of Claim:	TP
		Claim No:	2071523004SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC1179G	Engine No:	1KD2177335
Make & Model:	TOYOTA HIACE, 3.0 D High-roof 14 Seater (A)	Chassis No:	JTFST22P000013358
Reg. Date:	11/04/2012 (Man. Year: 2012)	Odometer:	611295 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,644.30	4,570.50	3,073.80	40.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,940.00	1,940.00	1,000.00	34.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,584.30	6,510.50	4,073.80	38.49
Approved Total (Overridden) (\$\$)		5,200.00		
Nett Amount (\$\$)	10,584.30	5,200.00	5,384.30	50.87
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment:	04/03/2022	
Date Inspected:	04/03/2022	Inspected At: Stytech Auto Pte Ltd (HQ) 2 Kaki Bukit Ave 2 #02-30, Kaki Bukit Autohub Singapore 417921
Estimated Period of Repair:	6.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LEFT SLIDING DOOR	Badly Dented	1,840.70 F	*1,655.10 FL
2	1		*LEFT SLIDING DOOR GLASS SEALANT	Necessary	60.00 FS	*40.00 FS
3	1		*LEFT SLIDING DOOR EXCURSION STICKER	Necessary	25.00 FS	*25.00 FS
4	1		*LEFT SLIDING DOOR SIDE SKIRT	Cracked	400.00 FS	*400.00 FS
5	1		*LEFT CENTER FENDER	Not Necessary	1,469.70 F	*- FL
6	1		*LEFT CENTER FENDER GLASS SEALANT	Not Necessary	40.00 FS	*- FS
7	1		*LEFT CENTER FENDER SIDE SKIRT	Cracked	300.00 FS	*300.00 FS
8	1		*LEFT REAR FENDER	Badly Dented	1,917.50 F	*1,917.50 FL
9	1		*LEFT REAR FENDER GLASS SEALANT	Necessary	60.00 FS	*40.00 FS
10	1		*LEFT REAR FENDER WHEEL ARCH SKIRT	Repair	250.00 FS	*- FS
11	1		*LEFT REAR CHROME SPORT RIM	Cut	500.00 FS	*500.00 FS
12	1		*REAR BUMPER	Cracked	781.40 F	*781.40 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,644.30	5,659.00
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	1,088.50
Total Parts (\$)	7,644.30	4,570.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSFER SLIDING DOOR GLASS	New	120.00	100.00
2	REMOVE & REFIX CENTER GLASS	New	100.00	0.00
3	REMOVE & REFIX REAR FENDER GLASS	New	120.00	100.00
4	TRANSFER SLIDING DOOR	New	150.00	60.00
5	REMOVE & REFIX INNER SEAT	New	250.00	100.00
6	CHECK WIRING	New	100.00	20.00
7	ANTI RUST PROOF	New	100.00	60.00
8	PANEL BEATING	New	800.00	700.00
9	PAINT WORK	New	1,200.00	800.00
Gross Labour Cost (\$\$)			2,940.00	1,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >