


ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: PC 1179G
 at Workshop m/s Stytech
 of _____
 Insured: SL S 2328A
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: \$7k.
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

3 023A

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

MA 440

Veh No: PC 1179G Yr Regn: 11/10/12
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CAI
 Make: Toyota Lince Minot c.c 2982
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 611295 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JTFST229 000013358
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: NI / S/Rim / STD A/Rim or
 Tyre Size: F: 225/55 R18
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: 6 mm Rear: 6 mm
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 1/3/22 D.O.I. 4/3/22
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 N/S Body
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

PC1179G SOL3A CORRECT 10-4-2022
 NO 32 Body bk.

22/3/22 4/5 \$5200 informed Winston

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

45140 700g

Not Approved
Heli
4/3/22
1/5 25200
Stamp

Vehicle:

PC1179G

Make & Model:

TOYOTA HIACE

Chassis No:

JTFST22P000013358

S/N	Parts/Labour	QTY	Unit Price	Price	Recommend
1	Left Silding Door		1655.10	\$ 1,840.70	Body 100 ✓
2	Left Silding Door Glass Sealant			\$ 60.00 SN	neu, 40 s/n
3	Left Silding Door "EXCURSION" Sticker			\$ 25.00 SN	neu / s/n
4	Left Silding Door Side Skirt			\$ 400.00 SN	cne / s/n
5	Left Center Fender			\$ 1,469.70	neu X
6	Left Center Fender Glass Sealant			\$ 40.00 SN	neu X
7	Left Center Fender Side Skirt			\$ 300.00 SN	cne ✓ s/n
8	Left Rear Fender			\$ 1,917.50	Body 100 ✓
9	Left Rear Fender Glass Sealant			\$ 60.00 SN	neu 40 s/n
10	Left Rear Fender Wheel ARC Skirt			\$ 250.00 SN	R X
11	Left Rear Chrome Sport Rim			\$ 500.00SN	cne ✓ s/n
12	Rear Bumper		252	\$ 781.40	cne ✓
Labour					
1	Transfer Silding Door Glass			\$ 120.00	100
2	Remove & Refix Center Glass			\$ 100.00	neu X
3	Remove & Refix Rear Fender Glass			\$ 120.00	100
4	Transfer Silding Door			\$ 150.00	60
5	Remove & Refix Inner Seat			\$ 250.00	100
6	Check Wiring			\$ 100.00	20
7	Anti Rust Proof			\$ 100.00	60
8	Panel Beating			\$ 800.00	700

9	Paint Work			\$ 1,200.00	800
---	------------	--	--	-------------	-----

STYTECH AUTO PTE. LTD.

2 Kaki Bukit Ave 2 #01-03
Kaki Bukit Autohub Singapore 417921
Tel: 6444 8125 Fax: 6445 3310
GST Reg. No.: 201601539K
Co. Reg. No.: 201601539K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 4354
257
P- 3265.50
S.N- 1305
L. 1940
6570.50
202
528.