

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22002026/AQY3N2**Date:** 09/06/2022**REFERENCE**

Insured/Claimant: KOK YEE CHUAN ELSON Policy No: DMPCSNW00124862101
Date of Loss: 26/02/2022 Nature of Claim: OD Claim No: SNM22D201457/C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMM7507L**
Make & Model: HYUNDAI AVANTE, 1.6 (A) Engine No: G4FGKU156967
Reg. Date: 12/07/2019 (Man. Year: 2019) Chassis No: KMHD841CMKU919965
Colour: Black Odometer: 93625 km
Engine Capacity: 1591 cc
Market Value/New Car Price: S\$75,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	31,635.64	16,891.40	14,744.24	46.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,750.00	3,760.00	990.00	20.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	36,385.64	20,651.40	15,734.24	43.24
Approved Total (Overridden) (S\$)		16,500.00		
- Excess (S\$)	500.00	500.00	0.00	0.00
Nett Amount (S\$)	35,885.64	16,000.00	19,885.64	55.41

INSPECTION

Date of Assignment: 03/03/2022

Date Inspected: 04/03/2022 Inspected At:

Hua Meng Spray Painting Workshop (HQ)
No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki
Bukit
Singapore 417883

Estimated Period of Repair: 11.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Jun 2022)
Parts:	143	HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM7507L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	548.00 FL	*548.00 FL
2	1		*FRONT BUMPER SIDE HOLDER	N/s Damaged	40.00 FL	*20.00 FL
3	1		*FRONT BUMPER LOWER LIP	Distorted	550.00 FL	*230.00 FL
4	1		*FRONT BUMPER LH FOD LAMP	Missing	185.30 FL	*185.30 FL
5	1		*FRONT BUMPER LH FOD LAMP GARNISH	Missing	40.00 FL	*40.00 FL
6	1		*FRONT BUMPER REINFORCEMENT	Dented	765.60 FL	*589.00 FL
7	1		*FRONT BUMPER SPONGE	Cracked	122.10 FL	*122.10 FL
8	1		*FRONT BUMPER BRACKET	N/s Damaged	28.00 FL	*14.00 FL
9	1		*FRONT BUMPER LOWER GARNISH	Cracked	79.00 FL	*79.00 FL
10	1		*FRONT GRILLE	Cracked	1,336.50 FL	*1,213.40 FL
11	1		*FRONT ENGINE LOWER COVER	Torn	147.40 FL	*147.40 FL
12	1		*FRONT LH HEADLAMP	Cracked	1,992.60 FL	*1,992.60 FL
13	1		*FRONT RESORNATOR	Cracked	124.80 FL	*124.80 FL
14	1		*FRONT LH FENDER	Distorted	1,350.50 FL	*1,227.70 FL
15	1		*FRONT LH FENDER INNER SHIELD	Missing	94.60 FL	*94.60 FL
16	1		*FRONT LH FENDER INNER SIDE GARNISH	Deformed	52.00 FL	*52.00 FL
17	1		*FRONT LH FENDER QUARTER GARNISH	Missing	23.10 FL	*23.10 FL
18	1		*FRONT BONNET	Dented	2,479.20 FL	*2,253.80 FL
19	1		*FRONT LH DOOR	Dented	2,192.30 FL	*1,785.00 FL
20	1		*FRONT LH DOOR TOP HINGE	Bent	45.20 FL	*45.20 FL
21	1		*FRONT LH DOOR LOWER HINGE	Bent	45.20 FL	*45.20 FL
22	1		*FRONT LH DOOR STOPPER	Not Necessary	47.10 FL	*- FL
23	1		*FRONT LH DOOR INNER LOCK	Damaged	217.20 FL	*217.20 FL
24	1		*FRONT LH DOOR WEATHER STRIP	Not Necessary	126.50 FL	*- FL
25	1		*FRONT LH DOOR INNER BOARD	Cracked	832.70 FL	*756.90 FL
26	1		*FRONT LH DOOR POWER WINDOW MOTOR	Not Necessary	327.80 FL	*- FL
27	1		*FRONT LH DOOR POWER WINDOW REGULATOR	Not Necessary	276.10 FL	*- FL
28	1		*FRONT LH SHOCK ABSORBER	Bent	410.30 FL	*410.30 FL
29	1		*FRONT LH DRIVE SHAFT	Not Necessary	1,030.70 FL	*- FL
30	1		*FRONT LH LOWER ARM	Bent	326.70 FL	*326.70 FL
31	1		*FRONT LH KNUCKLE ARM	Damaged	429.50 FL	*429.50 FL
32	1		*FRONT LH KNUCKLE ARM BEARING	Damaged	498.30 FL	*280.00 FL
33	1		*FRONT LH LINKAGE	Bent	98.90 FL	*98.90 FL
34	1		*FRONT SUPPORT PANEL	Cracked	1,045.00 FL	*949.00 FL
35	1		*STEERING RACK	Not Necessary	1,171.40 FL	*- FL
36	1		*REAR LH SHOCK ABSORBER	Not Necessary	263.10 FL	*- FL
37	1		*REAR AXLE	Bent	1,307.90 FL	*1,307.90 FL
38	1		*REAR LH DOOR	Dented	2,362.70 FL	*1,810.00 FL
39	1		*REAR LH DOOR TOP HINGE	Not Necessary	45.20 FL	*- FL
40	1		*REAR LH DOOR LOWER HINGE	Not Necessary	45.20 FL	*- FL
41	1		*REAR LH DOOR STOPPER	Not Necessary	53.00 FL	*- FL
42	1		*REAR LH DOOR INNER LOCK	Not Necessary	211.20 FL	*- FL
43	1		*REAR LH DOOR WEATHER STRIP	Not Necessary	126.50 FL	*- FL
44	1		*REAR LH DOOR INNER BOARD	Cracked	832.70 FL	*595.00 FL
45	1		*REAR LH DOOR POWER WINDOW MOTOR	Not Necessary	177.10 FL	*- FL
46	1		*REAR LH DOOR POWER WINDOW REGULATOR	Damaged	246.40 FL	*246.40 FL

Report was unsubmitted during this print-out.

6/9/22, 1:38 PM				Adjuster Report		
No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR LH DOOR PILLAR	Repair	4,922.70 FL	*- FL
48	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
49	1		*SET FRONT LH FENDER INNER SHIELD CLIPS	Necessary	60.00 FS	*30.00 FS
50	1		*SET FRONT LH DOOR BLACK STICKER	Necessary	38.50 FS	*38.50 FS
51	1		*FRONT LH SPORT RIM	Cut	1,299.00 FS	*750.00 FS
52	1		*FRONT LH TYRE	Punctured	380.00 FS	*180.00 FS
53	1		*FRONT NUMBER PLATE	Cracked	50.00 FS	*30.00 FS
54	1		*FRONT NUMBER PLATE HOLDER	Cracked	50.00 FS	*30.00 FS
55	1		*SET REAR LH DOOR BLACK STICKER	Necessary	38.50 FS	*38.50 FS
56	1		*REAR LH SPORT RIM	Cut	1,299.00 FS	*750.00 FS
57	1		*REAR LH TYRE	Not Necessary	380.00 FS	*- FS
58	1		*AIR CLEANER HOSE	Not Necessary	96.00 F	*- FN
59	1		*AIR CLEANER ASSY	Cracked	216.00 F	*216.00 FN
60	1		*FUEL BOX ASSY	Cracked	3,930.00 F	*292.00 FN
F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.						
Sub Total (S\$)					37,570.30	20,645.00
- List Item Discount on L Items 20.00/20.00% (S\$)					5,934.66	3,652.00
- Nett Item Discount on N Items 0.00/20.00% (S\$)					0.00	101.60
Total Parts (S\$)					31,635.64	16,891.40
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RESET	New	100.00	0.00
2	TO CHECK WHEEL ALIGNMENT	New	100.00	80.00
3	TOWING FEE	New	100.00	80.00
4	REMOVE & REINSTALL AIRCOND FILL IN GAS	New	150.00	120.00
5	REMOVE & REFIX LH SIDE FRONT AND REAR SUSPENSION	New	600.00	420.00
6	REMOVE & REINSTALL DOOR GLASS	New	300.00	160.00
7	REMOVE & REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	1,800.00	1,500.00
8	RESPRAY PAINTING	New	1,600.00	1,400.00
Gross Labour Cost (\$\$)			4,750.00	3,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >