

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE I	PTE LTD		Ref:	CS3/ASM22002027/Vvy3e2
	8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811			Date:	24/03/2022
	ATTN: LOH CYNTH	·IIA		Code:	ASM
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHD 4280R	Veh. Inspected	l	GW 6169D
	Policy No.	VFX/P2419138	Coverage (\$)		0.00
	Claim No.	S2M03URZ	Excess (\$)		0.00
	Assign From	LOH CYNTHIA	Assign Date		04/03/2022
2. Vehicle Particulars & Condition					
	Make & Model	NISSAN CABSTAR	c.c		3153
	Engine No.	HIDDEN	Year of Reg.		2003
	Chassis No.	JN1SF4F23Z0850954	Colour		GOLD
	Odometer	517997 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	195 R15C	LINAM		5 mm
	L/H Front Tyre	195 R15C	LINAM		5 mm
	R/H Rear Tyre	195 R15C	LINAM		5 mm
	L/H Rear Tyre	195 R15C	LINAM		5 mm
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5.	General Information				
	Accident Date	02/03/2022	Inspect Date /	Time	04/03/2022 ( 05:00 PM )
	Survey held at	SPEEDWERKZ PTE LTD			
	13 KAKI BUKIT ROAD 4, #01-20, BARTLEY BIZ CENTRE, SINGAPORE 417807				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				

Report Ref No. CS3/ASM22002027/Vvy3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser