

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD Ref: CS3/ASM22002028/Eqy3e2 8 SHENTON WAY #24-01 AXA TOWER Date: 06/04/2022 SINGAPORE 068811 ATTN: ONG KIAN THENG DERICK Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **SHA 3813B** SKA 5225A Veh. Inspected Policy No. VFX/P2419138 Coverage (\$) 0.00 Claim No. S2M03US7 Excess (\$) 0.00 ONG KIAN THENG DERICK **Assign Date** 04/03/2022 Assign From **Vehicle Particulars & Condition** 2. HONDA C-HR Make & Model 1797 c.c HIDDEN 2018 Engine No. Year of Reg. ZYX102118042 WHITE Chassis No. Colour Odometer 70612 KM Steering IN ORDER **IN ORDER** SPORTS RIM **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 215/60 R17 MICHELIN 4 mm 215/60 R17 **MICHELIN** L/H Front Tyre 4 mm 215/60 R17 **MICHELIN** R/H Rear Tyre 4 mm **MICHELIN** 4 mm L/H Rear Tyre 215/60 R17 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. 5. **General Information** 02/03/2022 04/03/2022 ( 03:27 PM ) Inspect Date / Time Accident Date V-TECH AUTO SERVICE Survey held at No.1 SOON LEE STREET #06-04/05/06/07 PIONEER CENTRE SINGAPORE 627605 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$10,000-\$12,000 5b. **Estimate Days of Repair** 

Report Ref No. CS3/ASM22002028/Eqy3e2

Inspected By

CHEN TSUE YEE

TSUE YEE

ESTIMATED NORMAL PERIOD FOR REPAIR:

**Automotive Assessor** 

L

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser

14 Working Days