#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/III22002032/TTY3E2

23/03/2022 Date:

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd Policy No: D22MFL0000974

**Claimant Vehicle SLG7183E** Insured Vehicle No: SLL8980M

No:

Date of Loss: 01/03/2022 Nature of Claim: ΤP Claim No: MFL2022D0001212

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: **SLG7183E** 

HONDA GRACE, 1.5 HYBRID DX CVT ABS D/AIRBAG Make & Model: Engine No: LEB5254655

11/10/2016 (Man. Year: 2016) Chassis No:

GM41104643 Reg. Date: Colour: White Odometer: 165821 km

**Engine Capacity:** 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price** 

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Handbrake (Serviceable): Yes **Engine Modification:** No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/45 R17 Rear Tyre Size: 205/45 R17 Front Left Side: Rear Left Side: Habilead 6 mm Habilead 6 mm Rear Right Side: Front Right Side: Habilead 6 mm Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

**INSPECTION** 

Date of Assignment: 04/03/2022

Hock Motors Workshop (HQ)

NO 1 KAKI BUKIT AVENUE 6, #02-38 AUTOBAY Date Inspected: 10/03/2022 Inspected At:

@ KAKI BUKIT

Singapore 417883

Estimated Period of Repair: 0.0 days

Adjuster: MOHD TAUFIKH BIN HAMID DENISE TAY KWEE CHENG Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

# **REPAIR DETAILS**

### Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Mar 2022)

Parts: 192 HONDA GRACE 1.5 HYBRID DX CVT ABS D/AIRBAG (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List) **Print Code:** (Unsubmitted, no print-code for SLG7183E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

There are no new parts selected.

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## **Recommended Labour**

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >