				COMFORTDELGRO				
	Job Ref No :	305504721		ENGINEERING				
Date		15/02/22		ComfortDelGro Engineering P				
FINA	ALIZATION FORM				oyang Drive Singapore 508969 6546 8156			
To :		LKK		Fax	;			
Attn	:	THEVAN						
Vehi	cle Reg No. : SH	8244T		Date of Accider	nt:09/02/22			
The:	survey and estimates o	of the repairs of the a	above-mention	ed vehicle are a	s follows:-			
1.	The repair job shall b	oill to:	NTUC	***	SJE4763K			
2.	The finalized amount	shall be:						
	(a) Spare Parts af							
	(b) Labour Charge	Labour Charges (include advertisement stickers etc.if any)						
	, .	By-Part Repair Co						
	(c.) Lumpsum Rep	air (if applicable)			\$1,300.00			
		Total for Lumpsum repair cost after Less: 20% Final Lumpsum Repair cost						
	rillai Lumpsu	iii Kepaii cost			\$1,300.00			
5.	Thank you for your as:	sistance. We confir finalized a			estimates and			
	Signature :	LIMI	S	ignature :	М			
1	Name : LIMTS	<u> </u>	_ 	ame :	THEVAN			
Tel : 62148398			– D	Date : 11/3/72				
	ax : 6546815		-					
or Offi	cial Use Only			r) %				
Item		Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks			
Rental Rate P/Day			YES					
Loss of Income Paid			N					
Survey Fees								
LTA Search Fee		\$7.49 /\$2.00						
Medical Fees (on behalf of driver, if applicable)								
Overru	חו							
narks:								

## COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Effective Date: 1 Nov 2020

DATE:

11-Feb-22

INSURANCE: NTUC

MODEL:

Hyundai i40

MVA: LIM TS

VEHICLE NO .: SH 8244T

	DECORIDION	QTY	UNIT PRICE	AMOUNT
PART NO.	DESCRIPTION			Cur
	Rear Bumper Rear Bumper Under Cover Rear Bumper Sponge Rear Bumper Reinforcement Rear Bumper Reinforcement Bracket RH / LH	1 1 1 1 2	\$80.30	\$553.00 / CUP \$228.00 / SCV \$119.50 / XSVC \$428.40 / XSVC \$160.60 / XSVC \$22.00 / YVC
	Rear Bumper Clips  SUB TOTAL LESS 20%	10	\$2.20	\$1,511.50 \$302.30 <b>\$1,209.20</b>
	DISCOUNTED TOTAL  Rear Bumper Adv.Sticker  Reverse Sensors	1		\$50.00 / hall \$135.70 / (UK
	S/NETT SUB LESS 10% S/NETT TOTAL			\$185.70 \$18.70 <b>\$167.13</b>
	Rear Bumper Plate Rear Bumper Adv.Sticker Rear Fender Adv.Sticker RH / LH	2	\$100.00	\$50.00 7 SUC \$50.00 / WC \$200.00 / WC
	NETT TOTAL			\$300.00
	SPARE PARTS TOTAL			\$1,676.33
	Labour Charge Panel Beating Spray Painting Charge R/I Reverse Sensors			\$300.00 \$300.00 \$120.00
	TOTAL LABOUR			\$720.00
	ESTIMATE TOTAL			\$2,396.33

This is an initial estimate based on a visual inspection of the above vehicle. The final vehicle is surveyed by a motor Surveyor appointed by the insurance company.

CERRITACHER CONSTITUTE THE ACCOUNT OF THE PROPERTY CONTROL OF THE PROPERTY OF the Repairer of the following:

Thuran 87235769

11/2/27 1630 C/S affur repu, v phoho 2 days w/2

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and whilect to final approval from Insurance Company

Tarritor