

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III22002036/KQY3E2

Date: 23/05/2022

REFERENCE

Insured/Claimant: COMFORTDELGRO RENT-A-CAR PTE LTD Policy No: D18MFL0003414_02

Date of Loss: 03/03/2022

Nature of Claim: OD

Claim No: MFL2022D0001045

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR1871Y	Engine No:	2ZR2G20415
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Chassis No:	JTDKB3FU403090542
Reg. Date:	23/12/2019 (Man. Year: 2019)	Odometer:	102464 km
Colour:	Metallic Silver		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	S\$112,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 9 mm	Rear Left Side:	Davanti 6 mm
Front Right Side:	West Lake 9 mm	Rear Right Side:	Davanti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,052.07	11,665.20	2,386.87	16.99
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	2,700.00	1,920.00	780.00	28.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,763.07	13,596.20	3,166.87	18.89
- Excess (S\$)	0.00	1,500.00	-1,500.00	
(S\$)	16,763.07	12,096.20	4,666.87	27.84
+ GST 7.00/7.00% (S\$)	1,173.41	846.73	326.68	27.84
Nett Amount (S\$)	17,936.48	12,942.93	4,993.55	27.84

INSPECTION

Date of Assignment:	04/03/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Braddell)
Date Inspected:	04/03/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Braddell) 205 Braddell Road Singapore 579701
Estimated Period of Repair:	6.0 days		

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Apr 2022)
Parts:	144	TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMR1871Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Buckled	993.70 FL	*950.50 FL
2	1		*BONNET LOCK	Bent	145.90 FL	*132.60 FL
3	1		*BONNET HINGE LH	Distorted	65.20 FL	*65.20 FL
4	1		*BONNET HINGE RH	Distorted	65.20 FL	*65.20 FL
5	1		*BONNET INSULATOR	Serviceable	145.60 FL	*- FL
6	10		*BONNET INSULATOR CLIPS	Not Necessary	72.10 FL	*- FL
7	1		*HEADLAMP LH	Cracked	2,661.70 FL	*2,661.70 FL
8	1		*HEADLAMP LOWER BRACKET LH	Repair	79.60 FL	*- FL
9	1		*HEADLAMP RH	Mtg Cracked	2,661.70 FL	*2,661.70 FL
10	1		*HEADLAMP LOWER BRACKET RH	Repair	79.60 FL	*- FL
11	1		*FRT GRILLE	Broken	349.50 FL	*321.90 FL
12	1		*FRT GRILLE LOGO	Necessary	125.60 FL	*125.60 FL
13	1		*FRT BUMPER	Cracked	556.20 FL	*499.90 FL
14	1		*FRT BUMPER SIDE RETAINER RH	Distorted	85.20 FL	*85.20 FL
15	1		*FRT BUMPER SIDE RETAINER LH	Distorted	85.20 FL	*85.20 FL
16	1		*FRT BUMPER SPONGE	Cracked	88.20 FL	*88.20 FL
17	1		*FRT BUMPER UPPER REINFORCEMENT	Bent	716.60 FL	*696.40 FL
18	1		*FRT BUMPER LOWER REINFORCEMENT	Repair	246.10 FL	*- FL
19	1		*FRT BUMPER TOW COVER RH	Serviceable	32.60 FL	*- FL
20	1		*FRT BUMPER TOW COVER LH	Serviceable	32.60 FL	*- FL
21	1		*FRT BUMPER LOWER GRILLE	Serviceable	187.20 FL	*- FL
22	1		*FRT SUPPORT TOP PANEL	Buckled	379.60 FL	*379.60 FL
23	1		*FRT SUPPORT TOP PANEL GARNISH	Serviceable	283.90 FL	*- FL
24	1		*FRT BRACE PANEL	Repair	85.90 FL	*- FL
25	1		*AIRCON CONDENSOR	Punctured	1,789.30 FL	*1,336.60 FL
26	1		*RADIATOR	Punctured	2,218.90 FL	*1,841.80 FL
27	1		*RADIATOR FAN COWLING	Cracked	264.80 FL	*264.80 FL
28	1		*RADIATOR FAN MOTOR	Serviceable	702.80 FL	*- FL
29	1		*RADIATOR FAN BLADE	Serviceable	219.00 FL	*- FL
30	1		*FRT NUMBER PLATE	Missing	45.00 FS	*45.00 FS
31	1		*FRT NUMBER PLATE BASE (LONG)	Cracked	115.60 FL	*115.60 FL
Supplementary #1						
32	1		*FRT SUPPORT TOP PANEL RH	Buckled	80.00 FL	*80.00 FL
33	1		*FRT SUPPORT TOP PANEL LH	Buckled	80.00 FL	*80.00 FL
34	1		*FRT SUPPORT SIDE PANEL LH	Bent	255.00 FL	*255.00 FL
35	1		*FRT SUPPORT SIDE PANEL RH	Bent	255.00 FL	*255.00 FL
36	1		*FRT SUPPORT LOWER PANEL	Bent	435.00 FL	*409.90 FL
37	1		*FRT RH LOWER SIDE GUIDE	Cracked	76.00 FL	*76.00 FL
38	1		*FRT LH LOWER SIDE GUIDE	Cracked	76.00 FL	*76.00 FL
39	1		*LH TOP SIDE AIR GUIDE	Cracked	84.00 FL	*84.00 FL
40	1		*RH TOP SIDE AIR GUIDE	Cracked	84.00 FL	*84.00 FL
41	1		*FRT RH WINDSCREEN SIDE GARNISH	Dented	102.00 FL	*102.00 FL
42	1		*FRT LH WINDSCREEN SIDE GARNISH	Dented	102.00 FL	*102.00 FL
43	1		*FRT WIPER GARNISH	Dented	686.00 FL	*686.00 FL
44	1		*RH HORN	Dented	146.00 FL	*146.00 FL
45	1		*LH HORN	Dented	146.00 FL	*146.00 FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*COOLANT	Necessary	58.00 FL	*58.00 FL
47	1		*AIR DUCT	Dented	156.00 FL	*156.00 FL
48	1		*AIR INTAKE DUCT	Dented	136.00 FL	*136.00 FL
Supplementary #2						
49	1		*RADIATOR GRILLE TRIM	Distorted	96.00 FL	*96.00 FL
50	1		*FRT BUMPER TOP RUBBER SEAL	Necessary	88.00 FL	*88.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	18,721.10	15,538.60
- List Item Discount on L Items 25.00/25.00% (S\$)	4,669.03	3,873.40
Total Parts (S\$)	14,052.07	11,665.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCK, STRAIGHTEN AND RENEW ACCIDENT AREA SUCH AS BONNET, FRT BUMPER, FRT SUPPORT PANEL, BOTH FRT FENDER AND ETC	New	1,000.00	720.00
2	TO PUTTY AND RESPRAY ACCIDENT AREA SUCH AS BONNET, FRT BUMPER, FRT SUPPORT PANEL, BOTH FRT FENDER AND ETC	New	1,300.00	1,000.00
3	TO DISCHAGE AND CHARGE AIRCON GAS	New	100.00	100.00
4	TO RESET AND PROGRAM HEADLAMP SYSTEM	New	250.00	80.00
5	TO CHECK LIGHTING AND WRING	New	50.00	20.00
Gross Labour Cost (\$\$)			2,700.00	1,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >