

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMR 2387Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	RIGHT REAR FENDER	TO REPAIR SEE LABOUR	1,010.90	-
1	RIGHT REAR FENDER COWLING	NOT NECESSARY	89.00	-
1	RIGHT REAR FENDER GLASS MOULDING	NOT NECESSARY	110.00	-
1	RIGHT REAR DOOR	DENTED	988.00	988.00
1	RIGHT LOWER ROCKER PANEL GARNISH	BROKEN	550.00	400.00
	LESS 20% DISCOUNT		-549.58	-277.60
			2,198.32	1,110.40
	SPECIAL NETT ITEMS			
1	RIGHT REAR WHEEL CAP (SN)	NOT NECESSARY	195.00	-
1	RIGHT REAR FENDER COWLING CLIP (SN)	NOT NECESSARY	15.00	-
1	TUBE SEALANT (SN)	NOT NECESSARY	40.00	-
			250.00	-
	<u>LABOUR</u>			
	TO REMOVE & REFIT RIGHT REAR FENDER GLASS,REPLACE MOULDING & SEALANT.	NOT NECESSARY	60.00	-
	TO TRANSFER RIGHT REAR DOOR GLASS,MECHANISM PARTS.	NOT NECESSARY	40.00	-
	TO TUFF KOTE AFFECTED AREA.		60.00	30.00
	TO CUT/WELDING RIGHT REAR FENDER,REMOVE RIGHT REAR DOOR,RIGHT LOWER ROCKER PANEL GARNISH,REPAIR REAR BUMPER,REPLACE NECESSARY PARTS.		800.00	500.00
	TO PUTTY,RESPRAY PAINTING REAR BUMPER & REAR RIGHT FENDER INNER & OUTER,RIGHT REAR DOOR INNER & OUTER AND LOWER ROCKER PANEL GARNISH TO POLISH.		900.00	800.00
			1,860.00	1,330.00
	GRAND TOTAL		4,308.32	2,440.40



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	1,950.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/SMR22002038/Eqy3n2



Automotive Assessor

P

ANG BRYAN TANI

Automotive Assessor / Investigator