

PRIORITY SERVICES

Insurance Loss Adjusters and Motor Appraisers
Blk 779 #01-1545 Yishun Ave 2 Singapore 760779
Tel: 62934822 Fax: 62963283
E-mail: admin@priorityservices.sg

Date: 14 November 2019

Your Ref: 19.27368 S.CK.xy
Our Ref: TP-0052/11/19

M/s. AXA Insurance Pte Ltd
c/o. M/s. Seah Ong & Partners LLP
36 Robinson Road #12-03
City House
Singapore 068877

Attention: Ms. Heng Xin Yi

Madam,

Inspection of 2008 Honda S2000 (M)
Registration No.: SKU 2207 S
Odometer Reading: 126474 km
Chassis No.: AP21100221

We refer to your instructions to us to conduct a paper survey of the above vehicle. A pre-repair survey was conducted on 16-04-2019, followed by inspection of dismantled parts on 18-04-2019 and resurvey after repairs on 23-04-2019.

The following documents were received: -

- 1) Copy of survey report by M/s. Mc-Coy Appraiser Pte Ltd
- 2) 85 copies of photos depicting damages sustained by SKU 2207 S
- 3) Accident reports by drivers of SKU 2207 S and SJS 4616 D

The vehicle sustained rear damages during an accident on 10-04-2019.

Repair cost submitted was \$4,800.00 lump-sum.

We append below our findings: -

<u>Replacement of Parts</u>		<u>Revised Amount</u>	<u>Our Recommendation</u>
1pc.	Boot lid logo – not necessary	\$ 37.40	\$ -
1pc.	Rear tail lamp o/s – refitted	885.90	-
1pc.	Rear bumper – repaired	1,593.10	-
2pcs.	Rear bumper side retainers – not necessary	47.00	-
1set	Rear number plate lamp	38.20	38.20
1pc.	Rear exhaust silencer – refitted	1,998.90	-

2pcs.	Rear exhaust silencer mountings -- serviceable	\$ 37.40	\$ -
		<u>=====</u>	<u>=====</u>
		\$ 4,637.90	\$ 38.20
	Less 20%	927.58	7.64
		<u>=====</u>	<u>=====</u>
		\$ 3,710.32	\$ 30.56

Special Nett Items:-

1pc.	Rear reverse camera -- serviceable	\$ 480.00	\$ -
1pc.	Rear number plate	45.00	45.00
		<u>=====</u>	<u>=====</u>
	Total For Parts:-	\$ 4,235.32	\$ 75.56
		<u>=====</u>	<u>=====</u>

Labour Charges:-

To remove and refit rear electrical wiring, replaced damaged lamps and test for proper functioning.	\$ 40.00	\$ 30.00
To remove and refit inner trims, inner garnishes to facilitate the repairs.	80.00	80.00
To remove and refit, straighten and readjust exhaust pipe and replace rear exhaust silencer and mountings.	100.00	100.00
To remove and replace the above damaged parts, straighten, knock out, realign and repair. To readjust to the original position using power tools.	750.00	400.00
To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	750.00	400.00
To apply undercoating on the repaired and replaced panels for rust protection.	60.00	30.00
	<u>=====</u>	<u>=====</u>
Total:-	\$ 6,015.32	\$ 1,115.56
	<u>=====</u>	<u>=====</u>

Lump-sum repairs:	\$ 4,800.00	\$ 900.00
-------------------	-------------	-----------

Estimated period of repairs: 3 working days

Pre-accident Market Value : About \$ 92,000.00
COE rebate : \$ 43,269.00


Vehicle within economical limit to repair.

We leave the decision of settlement to you.

Assuring you of our best services always


Yours faithfully

PRIORITY SERVICES



JIMMY S. T. LEE AMSOE, AMIRTE, MSAAA
Motor Appraiser

Surveyed by:



LAWRENCE NG, MSAAA
Motor Appraiser