



No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883
Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

Report Reference : TP / 19022-04/AY / 2019
Date of Report : 14 May 2019

Chau Gia-Leung
BLK 1 Pine Close
#10-167
Singapore 390001

THIRD PARTY SURVEY ACCIDENT HAPPENED ON 10 Apr 2019

Workshop Address : Boon Siong Vehicles Service
No.1 Kaki Bukit Avenue 6
#01-103 Auto Bay@Kaki Bukit
Singapore 417883

As per your instruction dated **16 Apr 2019** with regard to the above matter. We have carried out a physical inspection on the said vehicle **SKU 2207 S**. We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No	: SKU 2207 S	Engine No	: F22C1010226
Model	: Honda S2000	Mileage	: 126474
Year / Capacity	: 2008/2156	Colour	: White
Chassis No	: AP2-1100221		

2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT O/S	: 215/45 R17	Yokohama	5.00	mm	Sport
REAR O/S	: 245/40 R17	Yokohama	5.00	mm	Sport
FRONT N/S	: 215/45 R17	Yokohama	5.00	mm	Sport
REAR N/S	: 245/40 R17	Yokohama	5.00	mm	Sport



No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883
Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 6 working days to complete.

5. Enclosed number of photograph : 85 copies.

6. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey was done on a **"Without Prejudice"** basis. We hope that this report will be of assistance to you in dealing with the matter.

7. Should you discover any discrepancy in the report, please kindly notify us **within 2 weeks**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: **SKU 2207 S**
 Report No: **TP/ 19022-04/AY / 2019**

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
1	Boot lid	Repair	\$ 1034.30	\$
1	Boot lid lock	Intact	\$ 283.50	\$
1	Boot lid rubber	Intact	\$ 134.10	\$
1	Boot lid logo	Necessary	\$ 37.40	\$ 37.40
2	Rear taillamps	O/S Damage	\$ 1771.80	\$ 885.90
1	Rear bumper	Damage	\$ 1593.10	\$ 1593.10
2	Rear bumper side retainers	Necessary	\$ 47.00	\$ 47.00
1	Rear number plate lamp (1 set)	Damage	\$ 38.20	\$ 38.20
1	Rear exhaust silencer	Damage	\$ 1998.90	\$ 1998.90
2	Rear exhaust silencer mountings	Necessary	\$ 37.40	\$ 37.40
			<u>\$ 6975.70</u>	<u>\$ 4637.90</u>
Discount		20.0%	\$ 1395.14	\$ 927.58
			<u>\$ 5580.56</u>	<u>\$ 3710.32</u>
<u>Special Nett Items</u>				
1	Rear reverse camera	Damage	\$ 480.00	\$ 480.00
1	Rear number plate	Damage	\$ 50.00	\$ 45.00
			<u>\$ 530.00</u>	<u>\$ 525.00</u>

Spare Parts Total \$ 6110.56 \$ 4235.32

Vehicle No: **SKU 2207 S**
Report No: **TP/ 19022-04/AY / 2019**

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 6110.56	\$ 4235.32
1	To remove and refit rear electrical wiring, replaced damaged lamps and test for proper functioning.	\$ 50.00	\$ 40.00
2	To remove and refit inner trims, inner garnishes, to facilitate the repairs.	\$ 100.00	\$ 80.00
3	To remove and refit, straighten and re-adjust exhaust pipe and replace rear exhaust silencer and mountings.	\$ 150.00	\$ 100.00
4	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 1000.00	\$ 750.00
5	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 1000.00	\$ 750.00
6	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 150.00	\$ 60.00
Total		<u>\$ 8560.56</u>	<u>\$ 6015.32</u>

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 4800.00

SDLS: FOUR THOUSAND EIGHT HUNDRED ONLY



Qualified Appraiser

























































