



PRIORITY SERVICES

Insurance Loss Adjusters and Motor Appraisers
Blk 779 #01-1545 Yishun Ave 2 Singapore 760779
Tel: 62934822 Fax: 62963283
E-mail: admin@priorityservices.sg

Date: 14 November 2019

Your Ref: 19.27368 S.CK.xy

Our Ref: TP-0052/11/19

M/s. AXA Insurance Pte Ltd
c/o. M/s. Seah Ong & Partners LLP
36 Robinson Road #12-03
City House
Singapore 068877

Attention: Ms. Heng Xin Yi

Madam,

Inspection of 2008 Honda S2000 (M)
Registration No.: SKU 2207 S
Odometer Reading: 126474 km
Chassis No.: AP21100221

We refer to your instructions to us to conduct a paper survey of the above vehicle. A pre-repair survey was conducted on 16-04-2019, followed by inspection of dismantled parts on 18-04-2019 and resurvey after repairs on 23-04-2019.

The following documents were received: -

- 1) Copy of survey report by M/s. Mc-Coy Appraiser Pte Ltd
- 2) 85 copies of photos depicting damages sustained by SKU 2207 S
- 3) Accident reports by drivers of SKU 2207 S and SJS 4616 D

The vehicle sustained rear damages during an accident on 10-04-2019.

Repair cost submitted was \$4,800.00 lump-sum.

We append below our findings: -

<u>Replacement of Parts</u>	<u>Revised Amount</u>	<u>Our Recommendation</u>
1pc. Boot lid logo – not necessary	\$ 37.40	\$ -
1pc. Rear tail lamp o/s – refitted	885.90	-
1pc. Rear bumper – repaired	1,593.10	-
2pcs. Rear bumper side retainers – not necessary	47.00	-
1set Rear number plate lamp	38.20	38.20
1pc. Rear exhaust silencer – refitted	1,998.90	-

2pcs.	Rear exhaust silencer mountings – serviceable	\$ 37.40	\$ -
		<u>=====</u>	<u>=====</u>
		\$ 4,637.90	\$ 38.20
	Less 20%	927.58	7.64
		<u>=====</u>	<u>=====</u>
		\$ 3,710.32	\$ 30.56

Special Nett Items:-

1pc.	Rear reverse camera – serviceable	\$ 480.00	\$ -
1pc.	Rear number plate	45.00	45.00
		<u>=====</u>	<u>=====</u>
	Total For Parts:-	\$ 4,235.32	\$ 75.56
		<u>=====</u>	<u>=====</u>

Labour Charges:-

To remove and refit rear electrical wiring, replaced damaged lamps and test for proper functioning.	\$ 40.00	\$ 30.00
To remove and refit inner trims, inner garnishes to facilitate the repairs.	80.00	80.00
To remove and refit, straighten and readjust exhaust pipe and replace rear exhaust silencer and mountings.	100.00	100.00
To remove and replace the above damaged parts, straighten, knock out, realign and repair. To readjust to the original position using power tools.	750.00	400.00
To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	750.00	400.00
To apply undercoating on the repaired and replaced panels for rust protection.	60.00	30.00
	<u>=====</u>	<u>=====</u>
Total:-	\$ 6,015.32	\$ 1,115.56
	<u>=====</u>	<u>=====</u>
Lump-sum repairs:	\$ 4,800.00	\$ 900.00

Estimated period of repairs: 3 working days

Pre-accident Market Value : About \$ 92,000.00
COE rebate : \$ 43,269.00


Vehicle within economical limit to repair.

We leave the decision of settlement to you.

Assuring you of our best services always

Yours faithfully

PRIORITY SERVICES



JIMMY S. T. LEE AMSOE, AMIRTE, MSAAA
Motor Appraiser

Surveyed by:



LAWRENCE NG, MSAAA
Motor Appraiser

MC-COY

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883
Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

Report Reference : TP / 19022-04/AY / 2019
Date of Report : 14 May 2019

Chau Gia-Leung
BLK 1 Pine Close
#10-167
Singapore 390001

THIRD PARTY SURVEY ACCIDENT HAPPENED ON 10 Apr 2019

Workshop Address : Boon Siong Vehicles Service
No.1 Kaki Bukit Avenue 6
#01-103 Auto Bay@Kaki Bukit
Singapore 417883

As per your instruction dated **16 Apr 2019** with regard to the above matter. We have carried out a physical inspection on the said vehicle **SKU 2207 S**. We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No : SKU 2207 S
Model : Honda S2000
Year / Capacity : 2008/2156
Chassis No : AP2-1100221

Engine No : F22C1010226
Mileage : 126474
Colour : White

2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT O/S	: 215/45 R17	Yokohama	5.00	mm	Sport
REAR O/S	: 245/40 R17	Yokohama	5.00	mm	Sport
FRONT N/S	: 215/45 R17	Yokohama	5.00	mm	Sport
REAR N/S	: 245/40 R17	Yokohama	5.00	mm	Sport

Submit 4/5 \$2400
5 days



No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883
Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 6 working days to complete.

5. Enclosed number of photograph : 85 copies.

6. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey was done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.

7. Should you discover any discrepancy in the report, please kindly notify us within 2 weeks, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: **SKU 2207 S**
 Report No: **TP/ 19022-04/AY / 2019**

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
1	Boot lid	Repair	\$ 1034.30	\$ 111 X
1	Boot lid lock	Intact	\$ 283.50	\$ 111 X
1	Boot lid rubber	Intact	\$ 134.10	\$ 111 X
1	Boot lid logo	Necessary	\$ 37.40	\$ 111 37.40 X
2	Rear taillamps	O/S Damage	\$ 1771.80	\$ 511 885.90 X
1	Rear bumper	Damage	\$ 1593.10	\$ 111 1593.10 ✓
2	Rear bumper side retainers	Necessary	\$ 47.00	\$ 111 47.00 ✓
1	Rear number plate lamp (1 set)	Damage	\$ 38.20	\$ 111 38.20 ✓
1	Rear exhaust silencer	Damage	\$ 1998.90	\$ 111 1998.90 X
2	Rear exhaust silencer mountings	Necessary	\$ 37.40	\$ 111 37.40 X
			\$ 6975.70	\$ 4637.90
	Discount	20.0%	\$ 1395.14	\$ 927.58
			\$ 5580.56	\$ 3710.32
<u>Special Nett Items</u>				
1	Rear reverse camera	Damage	\$ 480.00	\$ 111 480.00 380
1	Rear number plate	Damage	\$ 50.00	\$ 111 45.00 ✓
			\$ 530.00	\$ 525.00

Spare Parts Total \$ 6110.56 \$ 4235.32

Vehicle No: **SKU 2207 S**
 Report No: **TP/ 19022-04/AY / 2019**


LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 6110.56	\$ 4235.32
1	To remove and refit rear electrical wiring, replaced damaged lamps and test for proper functioning.	\$ 50.00	\$ 40.00 30
2	To remove and refit inner trims, inner garnishes, to facilitate the repairs.	\$ 100.00	\$ 80.00 ✓
3	To remove and refit, straighten and re-adjust exhaust pipe and replace rear exhaust silencer and mountings.	\$ 150.00	\$ 100.00 ✓
4	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 1000.00	\$ 750.00 540
5	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 1000.00	\$ 750.00 500
6	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 150.00	\$ 11 60.00 X
Total		<u>\$ 8560.56</u>	<u>\$ 6015.32</u>

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 4800.00

SDLS: FOUR THOUSAND EIGHT HUNDRED ONLY


 Qualified Appraiser

P- 1678-30
 202
 P- 1342.64
 S.N- 425
 L- 1250
 3017.64
 2414