



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 1322J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	DOOR ASM-RR SI-1 (DISC 10%)	BENT	2,185.04	1,966.54
1	STICKER ELECTRIC (LOGO)(SN)	NECESSARY	21.60	21.60
1	STICKER STRIDES TAXI (DOOR)(SN)	NECESSARY	60.00	60.00
1	LATCH ASM RR S/D-L	NOT NECESSARY	139.98	-
1	LATCH ASM FRT S/D-L	NOT NECESSARY	156.84	-
1	MOTOR ASM-RR S/D WDO REG-L	NOT NECESSARY	169.00	-
1	HINGE ASM-RR S/D UPR-L	NOT NECESSARY	46.90	-
1	HINGE ASM-RR S/D LWR-L	NOT NECESSARY	47.22	-
1	MOTOR ASM-FRT S/D WDO REG-L	NOT NECESSARY	169.00	-
1	REGULATOR ASM-FRT S/D WDO-L	NOT NECESSARY	324.06	-
1	REGULATOR ASM-RR S/D WDO-L	NOT NECESSARY	265.30	-
1	TYRE	NOT NECESSARY	126.74	-
1	BRACKET-RR BPR FASCIA SI MTG	NOT NECESSARY	46.07	-
1	BRACKET ASM-RR BPR FASCIA SI-L	NOT NECESSARY	29.85	-
1	FASCIA-RR BPR	TO REPAIR SEE LABOUR	758.47	-
1	DOOR ASM-FRT SI-L	TO REPAIR SEE LABOUR	2,338.76	-
1	WHEEL	TO REPAIR SEE LABOUR	618.07	-
1	PANEL BODY SI-OTR-L	TO REPAIR SEE LABOUR	1,747.82	-
			9,250.72	2,048.14
<b><u>LABOUR</u></b>				
PANEL BEATING & BODY WORK.INCLUSIVE OF THE REPAIR OF FASCIA-RR BPR,DOOR ASM-FRT SI-L,WHEEL AND PANEL BODY SI-OTR-L.			3,600.00	800.00
SPRAY PAINT.			1,942.00	940.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING.			120.00	80.00
TO TRANSFER DOOR MECHANISM.			240.00	60.00
TO APPLY RUST-PROOFING ON AFFECTED AREA.			100.00	30.00

Report Ref No. NS/INC22002059/Ttce2



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE & REFIT REAR QUARTER GLASS LH.	NOT NECESSARY	120.00	-
	TO CHECK & RESET SYSTEM FUNCTION.		350.00	150.00
	ISOLATED OF (EV).		150.00	150.00
	TO CHECK WIRING AND SYSTEM FUNCTION.	NOT NECESSARY	80.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			6,862.00	2,210.00
<b>GRAND TOTAL</b>			<b>16,112.72</b>	<b>4,258.14</b>
<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>				<b>4,258.14</b>

Report Ref No. NS/INC22002059/Ttce2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.