

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22002060/AVCE2**Date:** 02/11/2022**REFERENCE**

Insured/Claimant:	YEO YU LING, ASHTON VIRGINIA	Policy No:	180002999
Date of Loss:	03/03/2022	Nature of Claim:	OD Claim No: 4753632712SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLX5189M		
Make & Model:	AUDI A3 SPORTBACK, 999cc TFSI S TRONIC (LED) (A)	Engine No:	CHZ424850
Reg. Date:	28/03/2018 (Man. Year: 2018)	Chassis No:	WAUZZZ8V3JA088987
Colour:	Red	Odometer:	40472 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$84,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	38,082.00	7,688.24	30,393.76	79.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	28,584.00	8,407.00	20,177.00	70.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	66,666.00	16,095.24	50,570.76	75.86
- Excess (\$\$)	600.00	600.00	0.00	0.00
(\$\$)	66,066.00	15,495.24	50,570.76	76.55
+ GST 7.00/7.00% (\$\$)	4,624.62	1,084.67	3,539.95	76.55
Nett Amount (\$\$)	70,690.62	16,579.91	54,110.71	76.55

INSPECTION

Date of Assignment:	07/03/2022		
Date Inspected:	04/03/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	7.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER-RH	Distorted	954.00 FS	*763.20 FS
2	1		*POP RIVET (8 Pcs)	Necessary	31.00 FS	*24.32 FS
3	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	75.00 FS	*- FS
4	1		*FRONT FENDER BRACKET-RH	Bent	56.00 FS	*44.40 FS
5	1		*FRONT FENDER CLOSING ELEMENT-RH LOWER	Not Necessary	68.00 FS	*- FS
6	1		*FRONT FENDER BRACE-RH	Not Necessary	107.00 FS	*- FS
7	1		*FRONT FENDER BRACKET END-RH	Bent	31.00 FS	*24.24 FS
8	1		*FRONT FENDER INSULATION-RH	Deformed	48.00 FS	*37.76 FS
9	1		*FRONT FENDER CLOSING ELEMENT-RH	Damaged	37.00 FS	*29.12 FS
10	2		*SPREADER RIVET	Necessary	4.00 FS	*2.88 FS
11	1		*FRONT WHEEL HOUSING LINER-RH	Torn	183.00 FS	*146.40 FS
12	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	60.00 FS	*- FS
13	1		*FRONT BUMPER	Not Necessary	2,146.00 FS	*- FS
14	1		*FRONT BUMPER GUIDE SECTION-RH	Not Necessary	43.00 FS	*- FS
15	1		*HEADLIGHT-RH	Not Necessary	5,455.00 FS	*- FS
16	1		*FRONT DOOR-RH	Distorted	2,973.00 FS	*2,378.40 FS
17	1		*FRONT DOOR OUTER SEAL-RH	Necessary	179.00 FS	*142.80 FS
18	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
19	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
20	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
21	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	252.00 FS	*- FS
22	1		*FRONT DOOR CATCH-RH	Not Necessary	105.00 FS	*- FS
23	1		*FRONT DOOR SEAL INNER-RH	Not Necessary	179.00 FS	*- FS
24	2		*FRONT DOOR HINGE UPPER-RH UPPER,LOWER	Not Necessary	91.00 FS	*- FS
25	2		*FRONT DOOR HINGE LOWER-RH UPPER,LOWER	Bent	89.00 FS	*36.00 FS
26	1		*TYRE PRESSURE DATA PLATE	Necessary	34.00 FS	*26.96 FS
27	1		*DATA LAG	Not Necessary	515.00 FS	*- FS
28	1		*FRONT DOOR WIRING SET	Not Necessary	642.00 FS	*- FS
29	1		*WING MIRROR MOUNTING-RH	Not Necessary	1,130.00 FS	*- FS
30	1		*FRONT DOOR WINDOW SLOT SEAL TRIM STRIP-RH	Not Necessary	302.00 FS	*- FS
31	1		*ROOF MOLDING-RH	Not Necessary	665.00 FS	*- FS
32	1		*WINDSCREEN WATER DEFLECTOR STRIP-RH	Not Necessary	75.00 FS	*- FS
33	1		*FRONT DOOR WINDOW GUIDE-RH	Not Necessary	467.00 FS	*- FS
34	1		*A-PILLAR-RH	Repair	3,734.00 FS	*- FS
35	1		*FRONT STONE CHIP GUARD-RH	Necessary	82.00 FS	*64.88 FS
36	1		*FRONT ADHESIVE TAPE	Not Necessary	59.00 FS	*- FS
37	1		*FRONT ALUMINIUM RIM	Cut	1,303.00 FS	*1,042.40 FS
38	4		*RUBBER VALVE	Necessary	15.00 FS	*5.92 FS
39	1		*TRACK CONTROL ARM	Bent	393.00 FS	*314.00 FS
40	1		*STABILIZER	Not Necessary	451.00 FS	*- FS
41	1		*FRONT WHEEL BEARING HOUSING	Damaged	627.00 FS	*501.20 FS
42	1		*FRONT WHEEL HUB BEARING	Damaged	553.00 FS	*442.00 FS
43	1		*FRONT WHEEL BEARING HOUSING GUIDE JOINT-RH	Damaged	134.00 FS	*107.20 FS
44	1		*COUPLING ROD	Not Necessary	105.00 FS	*- FS
45	1		*DRIVE SHAFT-RH	Not Necessary	1,517.00 FS	*- FS
46	1		*GAS SHOCK ABSORBER	Not Necessary	281.00 FS	*- FS
47	1		*TRACK ROD	Bent	98.00 FS	*78.40 FS
48	1		*TIE ROD END-RH	Damaged	126.00 FS	*100.40 FS
49	1		*STEERING GEAR	Not Necessary	5,538.00 FS	*- FS
50	1		*ASSEMBLY REINFORCEMENT	Not Necessary	1,105.00 FS	*- FS
51	1		*RUBBER BUSHES SET	Not Necessary	116.00 FS	*- FS
52	1		*FRONT DOOR CORNER TRIM-RH	Not Necessary	51.00 FS	*- FS
53	1		*PLENUM CHAMBER	Not Necessary	199.00 FS	*- FS
54	1		*FRONT WINDSCREEN	Not Necessary	1,206.00 FS	*- FS
55	1		*RAIN SENSOR GEL FOIL	Not Necessary	130.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*SPRING CLIP	Not Necessary	23.00 FS	*- FS
57	1		*ARYLIC SEALANT	Not Necessary	180.00 FS	*- FS
58	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
59	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
60	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
61	1		*FRONT WINDSCREEN SEALANT	Not Necessary	200.00 FS	*- FS
62	1		*RHS FRONT TYRE (NPA)	Not Necessary	0.00 FS	*- FS
63	1		*SUNDRIES	Necessary	600.00 FS	*155.20 FS
64	1		*REPAIR SET FOR STEERING GEAR BOX (Supplementary)	Necessary	50.00 FS	*39.92 FS
65	1		*A-PILLAR BRACKET-RH (Supplementary)	Bent	72.00 FS	*57.20 FS
66	1		*FRONT FENDER TOP COVER-RH (Supplementary)	Deformed	46.00 FS	*36.24 FS
67	1		*FRONT DOOR WIRING CONNECTOR (Supplementary)	Cracked	42.00 FS	*33.36 FS
68	1		*FRONT DOOR FOAM-RH (Supplementary)	Torn	14.00 FS	*11.04 FS
69	1		*ALUMINIUM RIM-LH REAR (Supplementary)	Cut	1,303.00 FS	*1,042.40 FS
					Total Parts (\$\$)	38,082.00 7,688.24

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	0.00
3	TO REMOVE AND TRANSFER RHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES	New	350.00	280.00
4	TO REMOVE AND REINSTALL FRONT SEAT ASSY,BACK REST,AB PILLAR TRIMS SILL TRIMS,CARPETS ELECTRONIC COMPONENTS AND FUSE TRAYS	New	1,800.00	0.00
5	TO REMOCE CENTER CONSOLE AND DASHBOARD ASSY FOR A-PILLAR RENEWAL INSPECT FOR DAMAGES	New	3,200.00	0.00
6	TO RENEW FRONT WINDSCREEN	New	480.00	0.00
7	TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN	New	400.00	0.00
8	TO CARRY OUT WATER SEEPAGE TEST FOR FRONT WINDSCREEN	New	200.00	0.00
9	TO CARRY OUT FIRST MEASUREMENT ON CAR-O LINER	New	800.00	0.00
10	TO SETUP THE VEHICLE ON CAR O-LINER TO FACILITATE THE REPAIR	New	2,400.00	0.00
11	TO REMOVE AND RENEW RHS FRONT WHEEL SUSPENSION ASSY SUBFRAME	New	2,400.00	2,400.00
12	TO DISMANTLE AND RENEW FRONT BUMPER,RHS FRONT FENDER AND RHS FRONT DOOR.CUT OUT AND REWELD RHS LOWER A-PILLAR AND RHS SILL PANEL.TO REPAIR RHS UPPER A-PILLAR AND BONNET.REINSTALL ALL PARTS REMOVED	New	6,300.00	2,000.00
13	TO RESPRAY FRONT BUMPER,RHS FRONT FENDER BONNET,RHS FRONT DOOR,RHS A-PILLAR,RHS SILL PANEL,ROOF CHANNEL AND DOOR ENTRANCES.TO CARRY OUT JOINT SEALANT WORKS AND STONE CHIP TREATMENT	New	6,500.00	2,200.00
14	TO RENEW RHS FRONT RIM WITH TYRE.TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	520.00	520.00
15	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	192.00
16	TO CUT AND WELD RHS A-PILLAR BRACKET (Supplementary)	New	1,400.00	500.00
17	TO RESPRAY RHS A-PILLAR BRACKET (Supplementary)	New	700.00	275.00
18	TO REMOVE AND RENEW LHS REAR RIM (Supplementary)	New	40.00	40.00
Gross Labour Cost (\$)			28,584.00	8,407.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >