



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SML 5183E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BONNET (WCP)	BUCKLED	260.00	260.00
2	BONNET HINGE L+R @\$30.00 (WCP)	BENT	60.00	60.00
2	HEADLAMP L+R @\$200.00 (WCP)	BROKEN	400.00	400.00
1	FRONT GRILLE LOGO (WCP)	SCRATCHED	30.00	30.00
1	FRONT GRILLE TRIM CTR (WCP)	DEFORMED	60.00	60.00
2	FRONT GRILLE TRIM L+R @\$40.00 (WCP)	CUT	80.00	80.00
1	FRONT GRILLE TOP SEAL (WCP)	BROKEN	25.00	25.00
1	FRONT GRILLE BASE (WCP)	CRACKED	70.00	70.00
10	FRONT GRILLE CLIP @\$2.50 (WCP)	NECESSARY	25.00	25.00
1	FRONT BUMPER (WCP)	DEFORMED	180.00	180.00
1	FRONT BUMPER GRILLE TOP (WCP)	BROKEN	30.00	30.00
1	FRONT BUMPER GRILLE (BIG) (WCP)	BROKEN	90.00	90.00
1	FRONT BUMPER GRILLE TOW COVER RH (WCP)	DEFORMED	15.00	15.00
2	FRONT BUMPER GRILLE TRIM L+R @\$40.00 (WCP)	NOT NECESSARY	80.00	-
1	FOGLAMP COVER LH (WCP)	NOT NECESSARY	65.00	-
10	FRONT BUMPER CLIP @\$2.50 (WCP)	NECESSARY	25.00	25.00
2	FRONT BUMPER SIDE RETAINER L+R @\$50.00 (WCP)	DEFORMED	100.00	100.00
1	FRONT BUMPER REINFORCEMENT (WCP)	BENT	160.00	160.00
1	FRONT SUPPORT PANEL (WCP)	BENT	280.00	280.00
2	FRONT FENDER L+R (NPA)	TO REPAIR SEE LABOUR	-	-
1	BONNET LOCK (ADDITIONAL) (WCP)	BENT	65.00	65.00
2	RADIATOR AIR GUIDE TOP LH & RH @\$45.00 (ADDITIONAL) (WCP)	DEFORMED	90.00	90.00
1	BRACE PANEL (ADDITIONAL) (WCP)	BENT	70.00	70.00
1	FRONT WIPER GARNISH (ADDITIONAL) (WCP)	CRACKED	300.00	300.00
1	FRONT FENDER COWLING CLAMP (ADDITIONAL) (WCP)	NECESSARY	6.00	6.00
1	FRONT FENDER COWLING CLAMP PIN (ADDITIONAL) (WCP)	NECESSARY	3.00	3.00
2	RADIATOR AIR GUIDE TOP BOTTOM LH & RH @\$45.00 (ADDITIONAL) (WCP)	DEFORMED	90.00	90.00

Report Ref No. CS6/AIS22002063/Gny3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	COST PLUS 10%		265.90	251.40
			2,924.90	2,765.40
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT NUMBER PLATE (SN)	BENT	40.00	40.00
1	COOLANT (SN)	NOT NECESSARY	40.00	-
			80.00	40.00
	<b><u>LABOUR</u></b>			
	TO INSPECT FRONT LIGHTINING MECHANISM & CHECK WIRING.		80.00	30.00
	TO KNOCK & STRAIGHTEN ON FRONT FENDER LH & RH. TO REMOVE & REPLACE FRONT SUPPORT PANEL. TO REMOVE & REPLACE DAMAGED ITEMS & REALIGN CONNECTION. INCLUSIVE OF THE REPAIR OF FRONT FENDER L+R.		800.00	800.00
	TO REMOVE & REFIT AIRCON CONDENSER & REFILL GAS.		80.00	60.00
	TO SPRAY PAINT ON REPAIRED AREAS.		900.00	900.00
	TO REMOVE & REFIT RADIATOR & FITTING.		80.00	60.00
			1,940.00	1,850.00
<b>GRAND TOTAL</b>			<b>4,944.90</b>	<b>4,655.40</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>4,655.40</b>

Report Ref No. CS6/AIS22002063/Gny3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.