5/24/22, 4:30 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III22002066/AEA3Q2

24/05/2022 Date:

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MPC0000187_03

Claimant Vehicle SMG5451H Insured Vehicle No: SKQ9051Z

No:

Date of Loss: 04/03/2022 Nature of Claim: TP Claim No: MPC2022D0001186

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMG5451H

HONDA JAZZ, 1.5 L (A) Make & Model: L15A71002923 Engine No:

Reg. Date: 13/10/2010 (Man. Year: 2008) Chassis No: JHMGE88509S202401

Colour: Odometer: 153955 km Blue

Engine Capacity: 1497 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition: No

CONDITION OF TYRES

Front Tyre Size: 195/50 R16 Rear Tyre Size: 195/50 R16 Front Left Side: Rear Left Side: Michelin 6 mm Michelin 6 mm Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,916.72	1,933.76	1,982.96	50.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,930.00	930.00	1,000.00	51.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,846.72	2,863.76	2,982.96	51.02
Approved Total (Overridden) (S\$)		2,300.00		
(S\$)	5,846.72	2,300.00	3,546.72	60.66
+ GST 7.00/7.00% (S\$)	409.27	161.00	248.27	60.66
Nett Amount (S\$)	6,255.99	2,461.00	3,794.99	60.66
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 07/03/2022

Ryder Auto Pte Ltd (HQ)

Date Inspected: 07/03/2022 Inspected At: 2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit

Singapore 417921

Estimated Period of Repair: 4.0 days

ADRIAN LING Adjuster: Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 May 2022)

Parts: 144 HONDA JAZZ 1.5 L (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMG5451H)

Particulars

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

Condition

Donairor's

Amount

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No. Oty Part No.

Qty Part No	Particulars	Condition	Repairer s	Amount
1	*FRONT BUMPER	Deformed	670.60 FL	*485.00 FL
10	*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
1	*FRONT BUMPER O/S RETAINER	Damaged	120.60 FL	*35.00 FL
1	*FRONT O/S HEAD LAMP	Cracked	1,466.40 FL	*748.00 FL
1	*FRONT O/S FOG-LAMP	Not Necessary	138.80 FL	*- FL
1	*FRONT O/S FOG-LAMP GARNISH	Cut	94.40 FL	*94.40 FL
1	*FRONT O/S FENDER	Buckled	432.30 FL	*432.30 FL
1	*FRONT O/S FENDER INNER TRIM	Not Necessary	211.40 FL	*- FL
1	*FRONT O/S FENDER PANEL	Repair	443.50 FL	*- FL
1	*FRONT O/S RIM	Cut	600.00 FS	*400.00 FS
1	*REAR O/S KNUCKLE	Not Necessary	310.00 FL	*- FL
1	*FRONT O/S BEARING	Not Necessary	135.40 FL	*- FL
1	*WIPER WASHER TANK	Deformed	85.00 FL	*85.00 FL
anchise part. S=Sp	Nett. L=ListItemDisc.	_		
		Sub Total (S\$)	4,738.40	2,309.70
	- List Item Discount	t on L Items 20.00/20.00% (S\$)	821.68	375.94
		Total Parts (S\$)	3,916.72	1,933.76
	10 1 1 1 1 1 1 1 1 1 1 1	10 *FRONT BUMPER CLIPS 1 *FRONT BUMPER O/S RETAINER 1 *FRONT O/S HEAD LAMP 1 *FRONT O/S FOG-LAMP 1 *FRONT O/S FOG-LAMP GARNISH 1 *FRONT O/S FENDER 1 *FRONT O/S FENDER INNER TRIM 1 *FRONT O/S FENDER PANEL 1 *FRONT O/S RIM 1 *REAR O/S KNUCKLE 1 *FRONT O/S BEARING 1 *WIPER WASHER TANK anchise part. S=SpcNett. L=ListItemDisc.	10 *FRONT BUMPER CLIPS Necessary 1 *FRONT BUMPER O/S RETAINER Damaged 1 *FRONT O/S HEAD LAMP Cracked 1 *FRONT O/S FOG-LAMP Not Necessary 1 *FRONT O/S FOG-LAMP GARNISH Cut 1 *FRONT O/S FENDER Buckled 1 *FRONT O/S FENDER INNER TRIM Not Necessary 1 *FRONT O/S FENDER PANEL Repair 1 *FRONT O/S RIM Cut 1 *REAR O/S KNUCKLE Not Necessary 1 *FRONT O/S BEARING Not Necessary 1 *FRONT O/S BEARING Not Necessary 1 *WIPER WASHER TANK Deformed anchise part. S=SpcNett. L=ListItemDisc. Sub Total (S\$) - List Item Discount on L Items 20.00/20.00% (S\$)	10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO DISMANTLE STRAIGHTEN AND WELDING FRONT DA PARTS	MAGE New	1,000.00	500.00
2	TO SPRAY PAINTING	New	700.00	400.00
3	TO REMOVE AND REFIT FRONT UNDER CARRIAGE	New	100.00	0.00
4	TO CHECK WIRING	New	80.00	30.00
5	TO RE-SEAL ANTI RUST	New	50.00	0.00
	G.	Gross Labour Cost (S\$)	1,930.00	930.00
	Report was unsubmitte	ed during this print-out		

< END OF ESTIMATES >