

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNB 8629H

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|---|---------------|-------------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | FRONT BUMPER (CONSISTENT) | NOT DAMAGED | 986.30 | - |
| 1 | FRONT BUMPER SIDE RETAINER (CONSISTENT) | NOT NECESSARY | 214.50 | - |
| 1 | FRONT DOOR RH (CONSISTENT) | DENTED | 1,211.40 | 1,029.00 |
| 1 | FRONT DOOR PROTECTOR (CONSISTENT) | MISSING | 515.70 | 435.00 |
| 1 | FRONT DOOR BLACK TAPE (CONSISTENT) | NECESSARY | 106.00 | 48.00 |
| 1 | FRONT DOOR OUTER HANDLE W/SENSOR (CONSISTENT) | NOT DAMAGED | 409.50 | - |
| 1 | FRONT DOOR WEATHERSTRIP(CONSISTENT) | TORN | 182.10 | 105.00 |
| 1 | FRONT DOOR REGULATOR (CONSISTENT) | BENT | 652.90 | 550.00 |
| 1 | FRONT DOOR REGULATOR MOTOR (CONSISTENT) | NOT DAMAGED | 348.00 | - |
| 1 | FRONT DOOR INNER LOCK (CONSISTENT) | NOT DAMAGED | 328.90 | - |
| 1 | FRONT DOOR LOCK STRIKER (CONSISTENT) | NOT DAMAGED | 86.50 | - |
| 1 | FRONT DOOR CHECKER ARM (CONSISTENT) | NOT DAMAGED | 102.80 | - |
| 1 | FRONT DOOR TRIMBOARD (CONSISTENT) | BROKEN | 696.90 | 600.00 |
| 1 | FRONT DOOR FRAME RUBBER (CONSISTENT) | NOT NECESSARY | 106.90 | - |
| 1 | REAR DOOR RH (CONSISTENT) | DENTED | 1,287.50 | 1,100.00 |
| 1 | REAR DOOR PROTECTOR (CONSISTENT) | BROKEN | 587.40 | 450.00 |
| 1 | REAR DOOR BLACK TAPE (CONSISTENT) | NECESSARY | 106.00 | 48.00 |
| 1 | REAR DOOR OUTER HANDLE W/SENSOR (CONSISTENT) | NOT DAMAGED | 409.50 | - |
| 1 | REAR DOOR WEATHERSTRIP (CONSISTENT) | NOT DAMAGED | 182.10 | - |
| 1 | REAR DOOR REGULATOR (CONSISTENT) | NOT DAMAGED | 652.90 | - |
| 1 | REAR DOOR REGULATOR MOTOR (CONSISTENT) | NOT DAMAGED | 348.00 | - |
| 1 | REAR DOOR INNER LOCK (CONSISTENT) | NOT DAMAGED | 328.90 | - |
| 1 | REAR DOOR LOCK STRIKER (CONSISTENT) | NOT DAMAGED | 86.50 | - |
| 1 | REAR DOOR CHECKER ARM (CONSISTENT) | NOT DAMAGED | 102.80 | - |
| 1 | REAR DOOR TRIMBOARD (CONSISTENT) | NOT DAMAGED | 696.90 | - |
| 1 | REAR DOOR FRAME RUBBER (CONSISTENT) | NOT DAMAGED | 106.90 | - |
| 1 | FRONT FENDER ARCH GARNISH (CONSISTENT) | CUT | 226.80 | 226.80 |
| 1 | FRONT FENDER (CONSISTENT) | DENTED | 879.50 | 879.50 |
| 1 | FRONT FENDER INNER COWLING (CONSISTENT) | NOT DAMAGED | 102.40 | - |
| 2 | FRONT SHOCK ABSORBER @\$368.70(CONSISTENT) | NOT DAMAGED | 737.40 | - |

Report Ref No. CC4/ASM22002068/Bea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|--|---------------|----------------------------|-------------------|
| 2 | FRONT WHEEL HUB BEARING @\$388.50(CONSISTENT) | NOT DAMAGED | 777.00 | - |
| 1 | ROCKER PANEL (CONSISTENT) | NOT DAMAGED | 867.00 | - |
| | LESS 25% DISCOUNT | | -3,608.48 | -1,367.83 |
| | | | 10,825.42 | 4,103.47 |
| | SPECIAL NETT ITEMS | | | |
| 1 | SUNDRIES (SN) (CONSISTENT) | NOT NECESSARY | 80.00 | - |
| 1 | FRONT DOOR SEALANT (SN) (CONSISTENT) | NECESSARY | 100.00 | 30.00 |
| 1 | FRONT DOOR TRIMBOARD CLIPS (SN) (CONSISTENT) | NECESSARY | 50.00 | 30.00 |
| 1 | FRONT FENDER SEALANT (SN) (CONSISTENT) | NECESSARY | 100.00 | 20.00 |
| 1 | FRONT FENDER INNER COWLING CLIPS (SN) (CONSISTENT) | NOT NECESSARY | 50.00 | - |
| 1 | FRONT BUMPER CLIPS (SN) (CONSISTENT) | NOT NECESSARY | 100.00 | - |
| 1 | TYRE (SN) (CONSISTENT) | NOT DAMAGED | 300.00 | - |
| 1 | RIM (SN) (CONSISTENT) | NOT NECESSARY | 350.00 | - |
| 1 | ROCKER PANEL SEALANT (SN) (CONSISTENT) | NOT NECESSARY | 100.00 | - |
| | | | 1,230.00 | 80.00 |
| | <u>LABOUR</u> | | | |
| | R&R FRONT DOOR COMPONENT. | | 150.00 | 80.00 |
| | WHEEL ALIGNMENT. | NOT NECESSARY | 180.00 | - |
| | R&R UNDER CARRIAGE. | NOT NECESSARY | 300.00 | - |
| | CHECK WIRING . | NOT NECESSARY | 100.00 | - |
| | DIAGNOSTIC RESET FAULT CODE. | NOT NECESSARY | 300.00 | - |
| | UPHOLSTERY. | NOT NECESSARY | 300.00 | - |
| | PANEL BEATING. | | 1,400.00 | 1,000.00 |
| | RUST PROOFING. | NOT NECESSARY | 200.00 | - |
| | SPRAY PAINTING. | | 1,400.00 | 600.00 |
| | | | 4,330.00 | 1,680.00 |
| | GRAND TOTAL | | 16,385.42 | 5,863.47 |



Page No.:3 of 3

| RECOMMENDED COST OF LUMP SUM REPAIRS | | 4,700.00 |
|--------------------------------------|--|----------|
| (TO ITS PRE-ACCIDENT CONDITION) | | |

Report Ref No. CC4/ASM22002068/Bea3q2



Automotive Assessor

HO LEONG CHUAN

Automotive Assessor