

ASS. REC. BY: Marcus

REF:

CC4/ASM22002071/4e23**ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

Veh No:

Yr Regn:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS, SI☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I: (\$

)

TOTAL

have GIA front portion centre NO Damage. Preli has Damage not due to accident
TP report only rear portion
17/3/22 4/5 @ 6400 informed E.I.

Ashur

AUTOWERKS**ZOOM AUTOWERKS PTE LTD**

130 Bedok Reservoir Road
 #08-1339 Singapore 470130
 Tel: 9450 7920
 * zoomautowerks@gmail.com

8 March 2022

REG NO.: SGZ 1619 P
 MAKE/MODEL: MINI ONE

mit Ashur
 7/3/22
 1/5 \$6400 8 days
 when photo after repair.

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	<u>LIST ITEMS</u>	
1	Rear windscreen moulding <i>all</i>	\$ 79.50
1	Rear tailgate <i>Body p.d</i>	\$ 1,235.50
2	Rear tailgate dampers <i>nec</i>	\$ 230.00
1	Rear tailgate inner board <i>all/cro</i>	\$ 285.00
1	Rear tailgate lock catch <i>all</i>	\$ 68.00
1	Rear tailgate lock <i>but/twi</i>	\$ 115.00
1	Rear tailgate outer chrome moulding <i>all</i>	\$ 298.00
1	Rear tailgate rubber <i>all</i>	\$ 155.00
1	Rear tailgate "Piccadilly" emblem <i>all</i>	\$ 80.00
1	Rear tailgate "One" emblem <i>all</i>	\$ 85.00
1	Rear taillamp o/s <i>cro 485</i>	\$ 796.00
1	Rear taillamp chrome rim o/s <i>cro 180</i>	\$ 370.60
1	Rear end panel <i>all/but 545</i>	\$ 550.00
1	Rear end panel inner garnish <i>twi</i>	\$ 195.00
1	Rear bumper <i>dis 880</i>	\$ 986.00
2	Rear bumper brackets <i>NN</i>	\$ 64.00
1	Rear bumper inner sponge <i>NF</i>	\$ 188.50
1	Rear bumper lower diffuser <i>dis</i>	\$ 321.40
1	Rear bumper reinforcement <i>but 545</i>	\$ 596.00
1	Rear bumper side retainer o/s <i>but/cro</i>	\$ 52.60
4	Rear bumper PDC sensors <i>shorted 180x2=360</i>	\$ 980.00 <i>2pcs</i>
2	Rear bumper tow hook covers <i>o/s m.s 28</i>	\$ 56.00 <i>1pc</i>
1	Rear third brake lamp <i>cro</i>	\$ 245.00
1	Rear third brake lamp chrome <i>cro</i>	\$ 56.00
1	Rear spare tyre board <i>all</i>	\$ 135.00
1	Rear spare tyre panel <i>R</i>	\$ 698.00
1	Rear exhaust silencer <i>all</i>	\$ 985.00
2	Rear exhaust mountings <i>all</i>	\$ 76.00
1	Rear air vent <i>Torn 115.00</i>	\$ 195.00
2	Rear fender inner shields <i>all</i>	\$ 260.00
1	Rear fender wheel arch garnish o/s <i>Torn</i>	\$ 330.00
		\$ 10,767.10
	Less 10%	\$ 1,076.71
		\$ 9,690.39

SPECIAL NETT ITEMS

1	Rear windscreen sealant	RM	\$	80.00	40
1	Rear bumper clip (1 set)	RM	\$	45.00	✓
1	Rear number plate with holder	RM	\$	50.00	X
1	Rear reverse camera	RM	\$	480.00	X
				\$	655.00

S/N

LABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.		\$	80.00	20
2	To remove and refit inner garnishes.		\$	150.00	80
3	To remove and refit rear reverse sensor and camera.		\$	150.00	50
4	To transfer rear tailgate mechanism and wiring assembly.		\$	120.00	60
5	To remove and refit rear windscreen glass.		\$	180.00	120
6	To remove, refit and replace exhaust silencer and mountings.	RM	\$	150.00	X
7	To apply undercoating.		\$	200.00	60
8	Panel beating.		\$	1,600.00	700
9	To re-spray painting on the affected areas.		\$	1,500.00	1050
				\$	4,130.00

GRAND TOTAL :

\$ 14,475.39

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-6448
102
P-5803-20
S.N- 85
L-2140
8028-2
202
6422