

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22002072/UPA3Q2**Date:** 02/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800068596-02
Claimant Vehicle No :	SJK5879Y	Insured Vehicle No :	GBH4717Z
Date of Loss:	03/03/2022	Nature of Claim:	TP
		Claim No:	5373623810SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJK5879Y	Engine No:	3ZZ4805460
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEE106121769
Reg. Date:	28/10/2008 (Man. Year: 2008)	Odometer:	324534 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,207.27	861.27	3,346.00	79.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,750.00	1,020.00	730.00	41.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,957.27	1,881.27	4,076.00	68.42
Approved Total (Overridden) (S\$)		1,500.00		
(S\$)	5,957.27	1,500.00	4,457.27	74.82
+ GST 7.00/7.00% (S\$)	417.01	105.00	312.01	74.82
Nett Amount (S\$)	6,374.28	1,605.00	4,769.28	74.82
+ Car Rental (2.0 x S\$100.00/day + 7.00% GST) (S\$)		214.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,821.00		

INSPECTION

Date of Assignment:	07/03/2022	
Date Inspected:	07/03/2022	Inspected At: Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6 Singapore 539365
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed / Torn	486.50 FL	*486.50 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	43.00 FL	*43.00 FL
3	2		*REAR BUMPER SIDE RETAINER	Not Necessary	140.80 FL	*- FL
4	1		*REAR BUMPER REFLECTOR O/S	Not Necessary	58.00 FL	*- FL
5	1		*REAR BOOT LID	Not Necessary	775.00 FL	*- FL
6	1		*REAR BOOT LID LAMP O/S	Not Necessary	355.00 FL	*- FL
7	1		*REAR BOOT LID OUTER CHROME MOULDING	Not Necessary	233.80 FL	*- FL
8	1		*REAR BOOT LID WEATHER STRIP	Not Necessary	185.00 FL	*- FL
9	1		*REAR BOOT LID TOYOTA LOGO	Not Necessary	58.60 FL	*- FL
10	1		*REAR BOOT LID 1.6 LOGO	Not Necessary	46.60 FL	*- FL
11	1		*REAR BOOT LID COROLLA LOGO	Not Necessary	61.00 FL	*- FL
12	1		*REAR BOOT LID ALTIS LOGO	Not Necessary	48.00 FL	*- FL
13	1		*REAR BOOT LID LX LOGO	Not Necessary	48.00 FL	*- FL
14	1		*REAR END PANEL	Repair	590.60 FL	*- FL
15	1		*REAR END PANEL INNER TRIM	Not Necessary	202.70 FL	*- FL
16	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
17	1		*REAR TAIL LAMP O/S	Not Necessary	460.00 FS	*- FS
18	2		*REAR BUMPER SIDE RETAINER	Repeated	140.80 FL	*- FL
19	1		*REAR END PANEL	Repeated	590.60 FL	*- FL
20	1		*REAR END PANEL INNER TRIM	Repeated	202.70 FL	*- FL
21	1		*REAR BUMPER SPONGE WITH BAR	Torn	395.00 FL	*284.20 FL
22	1		*O/S END PANEL BRACKET	Dented	68.00 FL	*68.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,389.70	1,081.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,182.43	220.43
Total Parts (\$\$)	4,207.27	861.27

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTYAND SPRAY PAINTING REAR OF THE AFFECTED PORTION	New	700.00	400.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTEN REAR OF THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	700.00	520.00
3	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	70.00	20.00
4	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	60.00	50.00
5	TO RUST-PROOFING OF THE AFFECTED AREAS	New	120.00	30.00
6	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	100.00	0.00
Gross Labour Cost (\$\$)			1,750.00	1,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >