

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22002073/UPA3Q2**Date:** 17/11/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210058459
Claimant Vehicle No :	SDR3390L	Insured Vehicle No :	GBB8342B
Date of Loss:	03/03/2022	Nature of Claim:	TP
		Claim No:	2648816581SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDR3390L	Engine No:	A25A0385624
Make & Model:	TOYOTA CAMRY, 2.5 (A)	Chassis No:	MR2B63HKX04002466
Reg. Date:	18/06/2019 (Man. Year: 2019)	Odometer:	63134 km
Colour:	White		
Engine Capacity:	2487 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/45 R18	Rear Tyre Size:	235/45 R18
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,511.67	3,086.47	2,425.20	44.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	1,010.00	590.00	36.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,111.67	4,096.47	3,015.20	42.40
Approved Total (Overridden) (\$\$)		3,250.00		
(\$\$)	7,111.67	3,250.00	3,861.67	54.30
+ GST 7.00/7.00% (\$\$)	497.82	227.50	270.32	54.30
Nett Amount (\$\$)	7,609.49	3,477.50	4,131.99	54.30
+ Car Rental (2.0 x S\$90.00/day + 7.00% GST) (\$\$)		192.60		
(\$\$)		3,670.10		
Liabe Amount (50.00%) (\$\$)		1,835.05		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		1,837.05		

INSPECTION

Date of Assignment: 07/03/2022

Date Inspected: 07/03/2022

Inspected At:

Tan Lim Motor Pte Ltd (Defu)
1 Defu Lane 6
Singapore 539365

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	596.90 FL	*596.90 FL
2	1		*FRONT BUMPER SIDE RETAINER N/S	Serviceable	98.00 FL	*- FL
3	8		*FRONT BUMPER CLIPS	Necessary	34.40 FL	*34.40 FL
4	1		*N/S HEADLAMP	Scratched	3,299.00 FL	*3,299.00 FL
5	1		*FRONT BUMPER SPONGE	Not Necessary	90.00 FL	*- FL
6	1		*N/S FRONT FENDER	Repair	801.00 FL	*- FL
7	1		*N/S FRONT FENDER VVT-I BADGE	Not fitted	41.10 FL	*- FL
8	1		*N/S FRONT FENDER INNER COWLING	Not Necessary	153.20 FL	*- FL
9	6		*N/S FRONT FENDER INNER COWLING CLIPS	Not Necessary	25.80 FL	*- FL
10	1		*N/S FRONT WHEEL RIM	Not Necessary	2,024.50 FL	*- FL
11	1		*N/S FRONT SENSOR	Shorted	185.00 FL	*185.00 FL
					Sub Total (\$\$)	7,348.90 4,115.30
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,837.23 1,028.83
					Total Parts (\$\$)	5,511.67 3,086.47

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	50.00	20.00
2	TO RUST-PROOFING OF THE AFFECTED AREAS	New	150.00	0.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION REMOVE AND RENEWAL OF PARTS ADJUST AND REALIGN THE SAME	New	600.00	400.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	600.00	550.00
5	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	100.00	40.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	100.00	0.00
Gross Labour Cost (S\$)			1,600.00	1,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >