

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22002088/UGA3Q2**Date:** 14/07/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070146585
<b>Claimant Vehicle No :</b>	SNE2168U	<b>Insured Vehicle No :</b>	SJX8299H
Date of Loss:	05/03/2022	Nature of Claim:	TP
		Claim No:	9217855408SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SNE2168U</b>		
Make & Model:	BMW 216D, 1.5 D Active Tourer (F45) D/AB LED (A)	Engine No:	30955029B37C15A
Reg. Date:	07/09/2017 (Man. Year: 2017)	Chassis No:	WBA2B32070V926039
Colour:	White	Odometer:	171331 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40Z R18	Rear Tyre Size:	245/40Z R18
Front Left Side:	Goform 6 mm	Rear Left Side:	Goform 6 mm
Front Right Side:	Goform 6 mm	Rear Right Side:	Goform 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,168.88	3,799.08	1,369.80	26.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,280.00	830.00	1,450.00	63.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,448.88</b>	<b>4,629.08</b>	<b>2,819.80</b>	<b>37.86</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,700.00</b>		
<b>(S\$)</b>	7,448.88	3,700.00	3,748.88	50.33
<b>+ GST 7.00/7.00% (S\$)</b>	521.42	259.00	262.42	50.33
<b>Nett Amount (S\$)</b>	<b>7,970.30</b>	<b>3,959.00</b>	<b>4,011.30</b>	<b>50.33</b>
<b>+ Car Rental (2.0 x S\$100.00/day + 7.00% GST) (S\$)</b>		214.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>4,175.00</b>		

INSPECTION

Date of Assignment:	07/03/2022	
Date Inspected:	07/03/2022	Inspected At: Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6 Singapore 539365
Estimated Period of Repair:	3.0 days	

**Adjuster:** MARCUS CHUA**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

*ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed / Torn	854.50 FL	*854.50 FL
2	1		*FRONT BUMPER BASE N/S	No such part	79.10 FL	*- FL
3	1		*FRONT BUMPER FOG LAMP N/S	Not Necessary	276.40 FL	*- FL
4	1		*FRONT BUMPER FOG LAMP TRIM N/S	Grazed	82.50 FL	*82.50 FL
5	1		*FRONT BUMPER FOG LAMP CHROME MOULDING N/S	Bent	95.00 FL	*95.00 FL
6	1		*FRONT BUMPER PARKING SENSOR	N/S Shorted	560.00 FL	*225.00 FL
7	6		*FRONT BUMPER PARKING SENSOR HOLDER	Not Necessary	510.00 FL	*- FL
8	1		*FRONT BUMPER SIDE RETAINER N/S	Cracked	19.00 FL	*19.00 FL
9	1		*HEADLAMP N/S	Cracked	2,348.50 FL	*2,348.50 FL
10	1		*HEADLAMP BRACKET N/S	No such part	145.90 FL	*- FL
11	1		*N/S FRONT FENDER	Bent / Warped	596.70 FL	*596.70 FL
12	1		*N/S FRONT FENDER INNER COWLING	Not Necessary	145.60 FL	*- FL
13	6		*N/S FRONT FENDER INNER COWLING CLIPS	Not Necessary	30.00 FL	*- FL
					Sub Total (\$)	5,743.20 4,221.20
					- List Item Discount on L Items 10.00/10.00% (\$)	574.32 422.12
					Total Parts (\$)	5,168.88 3,799.08

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	80.00	20.00
2	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	120.00	50.00
3	USING ONBOARD SCAN TOOL (OBD) PERFORM FULL ENGINE DIAGNOSTIC CHECK TO CONFIGURE AND CLEAR ,RESET SRS SERVICE LIGHT	New	450.00	60.00
4	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	80.00	0.00
5	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	750.00	300.00
6	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	800.00	400.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,280.00</b>	<b>830.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >